



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 5875E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	630.00	630.00
2	FRONT BUMPER SIDE RETAINER @\$62.30	NOT NECESSARY	124.60	-
1	FRONT BUMPER LOGO	NECESSARY	105.20	105.20
1	FRONT BUMPER DAY LIGHT	CRACKED	585.20	585.20
1	FRONT BUMPER DAY LIGHT UPPER GARNISH	DEFORMED	90.00	90.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	499.00	-
1	FRONT BUMPER REINFORCEMENT SPONGE	CRACKED	102.00	102.00
1	HEADLAMP	NOT NECESSARY	2,533.60	-
	LESS 25% DISCOUNT		-1,167.40	-378.10
			3,502.20	1,134.30
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
			20.00	20.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVAL AND REPLACING PARTS.		600.00	200.00
	TO SPRAY PAINT AFFECTED AREA.		600.00	200.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	WIRING CHECK.		180.00	30.00
			1,630.00	430.00
	GRAND TOTAL		5,152.20	1,584.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,250.00

Report Ref No. CS/AGI23000543/Aqy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.