3/15/23, 11:43 AM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.

Our File No: CS6/AIS23000551/DQY3M4

79 Robinson Road #09-01 Singapore 068897 **Date:** 15/03/2023

**REFERENCE** 

Insured/Claimant: NG WEI REN, DARYL Policy No: SP2002799658-01

Date of Loss: 12/01/2023 Nature of Claim: OD Claim No: 202332004632

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SNC3502S

Make & Model: MAZDA CX-5, 2.0 ELEGANCE 2WD I4 (A) Engine No: PE31709764

Reg. Date: 14/10/2021 (Man. Year: 2021) Chassis No: JM6KF2W7AN0696130

Colour: White Odometer: 13295 km

Engine Capacity: 1998 cc

Market Value/New Car

Price: S\$145,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/65 R17 Rear Tyre Size: 225/65 R17
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS               | Repairer's | Adjuster's | Difference | Diff % |
|------------------------------|------------|------------|------------|--------|
| Parts                        | 3,580.00   | 2,575.00   | 1,005.00   | 28.07  |
| Miscellaneous Items          | 0.00       | 0.00       | 0.00       |        |
| Labour                       | 960.00     | 400.00     | 560.00     | 58.33  |
| Paintwork Labour             | 680.00     | 400.00     | 280.00     | 41.18  |
| Towing                       | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$) | 5,220.00   | 3,375.00   | 1,845.00   | 35.34  |
| - Excess (S\$)               | 0.00       | 600.00     | -600.00    |        |
| (S\$)                        | 5,220.00   | 2,775.00   | 2,445.00   | 46.84  |
| + GST 8.00/8.00% (S\$)       | 417.60     | 222.00     | 195.60     | 46.84  |
| Nett Amount (S\$)            | 5,637.60   | 2,997.00   | 2,640.60   | 46.84  |

**INSPECTION** 

Date of Assignment: 17/01/2023 Present Location: Vin's Motor Pte Ltd (Sin Ming)

Vin's Motor Pte Ltd (Sin Ming)

Date Inspected: 18/01/2023 Inspected At: 160 Sin Ming Drive, #03-03, Sin Ming AutoCity

100 Sill Willig Drive, #03-03, Sill Willig Autoc

Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

|     | •            |          |               |        |
|-----|--------------|----------|---------------|--------|
| -   | $\sim$ $\pm$ | 0r       | $\sim$ $\sim$ | $\sim$ |
| ~ . |              |          |               |        |
| ,   | _            | $\sim$ 1 | C I I         | ce     |

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Mar 2023)

Parts: M1-SUV MAZDA CX-5 2.0 ELEGANCE 2WD I4 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNC3502S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### Recommended Parts

|        |                                  | Particulars                               | Condition                 | Repairer's  | Amount   |
|--------|----------------------------------|---|---------------------------|---|--|
| 1      |                                  | *FRONT GRILLE ASSY (order)                | Broken                    | 970.00 F  | *970.00 F  |
| 1      |                                  | *FRONT GRILLE EMBLEM (order) (WCP)        | Broken                    | 80.00 F   | *80.00 F   |
| 1      |                                  | *NOSE PANEL (order)<br>(WCP)              | Distorted                 | 260.00 F  | *260.00 F  |
| 5      |                                  | *NOSE PANEL RIVET (WCP)                   | Necessary                 | 20.00 F   | *20.00 F   |
| 1      |                                  | *FRONT BUMPER (order) (WCP)               | Broken                    | 950.00 F  | *950.00 F  |
| 1      |                                  | *FRONT BUMPER REINFORCEMENT (order) (WCP) | Not Necessary             | 480.00 F  | *- F   |
| 10     |                                  | *FRONT BUMPER CLIPS (WCP)                 | Necessary                 | 20.00 F   | *20.00 F   |
| 1      |                                  | *FRONT SUPPORT PANEL (WCP)                | Not Necessary             | 330.00 F  | *- F   |
| 1      |                                  | *FRONT SUPPORT TOP PANEL (WCP)            | Not Necessary             | 90.00 F   | *- F   |
| 1      |                                  | *FRONT NO.PLATE                           | Bent                      | 60.00 FS  | *45.00 FS  |
| nchise | part. S=SpcN                     | ett.                                      | _                         |   |  |
|        |                                  |   | Sub Total (S\$)           | 3,260.00  | 2,345.00   |
|        |                                  | + Margin on L,N Items                     | s 10.00/10.00% (S\$)<br>_ | 320.00  | 230.00   |
|        |                                  |   | Total Parts (S\$)         | 3,580.00  | 2,575.00   |
|        | 1<br>1<br>5<br>1<br>1<br>10<br>1 | 1 1 5 1 1 1 1 1 1 1 1 1 1                 | 1                         | 1 *FRONT GRILLE EMBLEM (order) (WCP) 1 *NOSE PANEL (order) (WCP) 5 *NOSE PANEL RIVET (WCP) 1 *FRONT BUMPER (order) (WCP) 1 *FRONT BUMPER REINFORCEMENT (order) (WCP) 1 *FRONT BUMPER CLIPS (WCP) 1 *FRONT SUPPORT PANEL (WCP) 1 *FRONT SUPPORT TOP PANEL (WCP) 1 *FRONT SUPPORT TOP PANEL (WCP) 1 *FRONT NO.PLATE  Bent  Inchise part. S=SpcNett.  Sub Total (\$\$) | Tender   T |

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No          | Particulars              | Lab.Type                              | Repairer's | Amount |
|-------------|--------------------------|---------------------------------------|------------|--------|
| <u>Pair</u> | ntwork Labour            |                                       |            |        |
| 1           | TO SPRAY PAINTING        | New                                   | 680.00     | 400.00 |
| Lab         | our Items                |                                       |            |        |
| 2           | TO RESET HEADLAMP SYSTEM | New                                   | 280.00     | 0.00   |
| 3           | TO REPAIR DAMAGES        | New                                   | 680.00     | 400.00 |
|             |                          | Gross Labour Cost (S\$)               | 1,640.00   | 800.00 |
|             | Report wa                | as unsubmitted during this print-out. |            |        |

< END OF ESTIMATES >