

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|--|--|-----------------|-------|-----------------------|
| | HSBC LIFE (SING) | APORE) PTE LTD | F | Ref: | CS/ASM23000559/Kvp3m4 |
| | 10 MARINA BOUL #48-01 MARINA B 2SINGAPORE 018 | AY FINANCIAL CENTRE TOWER | С | Date: | 09/02/2023 |
| | ATTN: OH VALE | | C | Code: | HSB |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SHC 994X | Veh. Inspected | | SLP 5059Y |
| | Policy No. | VFX/P2419140 | Coverage (\$) | | 0.00 |
| | Claim No. | S3M04I1B | Excess (\$) | | 0.00 |
| | Assign From | OH VALE | Assign Date | | 17/01/2023 |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | HONDA JAZZ (A) | c.c | | 1498 |
| | Engine No. | HIDDEN | Year of Reg. | | 2017 |
| | Chassis No. | JHMGK5850HX201674 | Colour | | METALLIC DARK BLUE |
| | Odometer | 53352 KM | Steering | | IN ORDER |
| | Brakes | IN ORDER | Modification | | STANDARD ALLOY RIM |
| | General | GOOD | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance |
| | R/H Front Tyre | 185/55 R16 | YOKOHAMA | | 8 mm |
| | L/H Front Tyre | 185/55 R16 | YOKOHAMA | | 8 mm |
| | R/H Rear Tyre | 185/55 R16 | YOKOHAMA | | 8 mm |
| | L/H Rear Tyre | 185/55 R16 | YOKOHAMA | | 8 mm |
| 4. | I. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 14/01/2023 | Inspection Date | | 19/01/2023 |
| | Survey held at | RIVERVIEW AUTO SERVICES PTE LTD | | | |
| | | 10 ANG MO KIO INDUSTRIAL PARK 2A #04-07 AMK AUTOPOINT SINGAPORE 568047 | | | |
| 5a. | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days | | | | |