

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000561/RQP3Q2**Date:** 08/03/2023REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00046052201

Claimant Vehicle No : SNB5037K **Insured Vehicle No :** SMJ5526K

Date of Loss: 12/01/2023 Nature of Claim: TP Claim No: SNM23D200385/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNB5037K**

Make & Model: SKODA OCTAVIA, 1.4 AMBITION PLUS (A) Engine No: DFY064592

Reg. Date: 26/08/2021 (Man. Year: 2021) Chassis No: TMBBR7NX9MY141413

Colour: White Odometer: 26111 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,945.35	8,268.24	1,677.11	16.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,510.00	6,710.00	5,800.00	46.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,455.35	14,978.24	7,477.11	33.30
+ GST 8.00/8.00% (S\$)	1,796.43	1,198.26	598.17	33.30
Nett Amount (S\$)	24,251.78	16,176.50	8,075.28	33.30

INSPECTION

Date of Assignment: 17/01/2023

Date Inspected: 18/01/2023 Inspected At: Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Mar 2023)
Parts:	143	SKODA OCTAVIA 1.4 AMBITION PLUS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB5037K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*UNBEKANNT REAR W/SCREEN	Necessary	939.32 FS	*939.32 FS
2	2		*1K WINDOW ADHESIVE	Necessary	101.46 FS	*101.46 FS
3	1		*ALL PURPOSE CLEANER	Necessary	84.67 FS	*84.67 FS
4	1		*PRIMER	Necessary	24.91 FS	*24.91 FS
5	1		*ACTIVATOR	Necessary	21.62 FS	*21.62 FS
6	2		*APPLICATOR	Necessary	18.38 FS	*18.38 FS
7	1		*UNBEKANNT REAR BOOTLID	Bent	4,419.55 FS	*4,419.55 FS
8	1		*UNBEKANNT BOOT LID LOCK	Not Necessary	100.61 FS	*- FS
9	4		*RIVELTED CAP NUT	Necessary	11.24 FS	*11.24 FS
10	1		*UNBEKANNT NAME PLATE -SKODA	Necessary	100.37 FS	*100.37 FS
11	1		*UNBEKANNT NAME PLATE -OCTAVIA	Necessary	100.37 FS	*100.37 FS
12	1		*UNBEKANNT NAME PLATE -ETEC	Necessary	100.37 FS	*100.37 FS
13	1		*REAR BUMPER	Deformed	1,843.66 FS	*1,843.66 FS
14	1		*UNBEKANNT TOWING COVER	Not Necessary	28.10 FS	*- FS
15	1		*SENSOR BRACKET	Necessary	18.66 FS	*18.66 FS
16	1		*SENSOR BRACKET	Necessary	18.66 FS	*18.66 FS
17	1		*SENSOR BRACKET	Necessary	18.66 FS	*18.66 FS
18	1		*SENSOR BRACKET	Necessary	18.66 FS	*18.66 FS
19	1		*SENSOR PRIMED	Not Necessary	194.63 FS	*- FS
20	1		*SEAL RING SATIN BLACK	Necessary	6.10 FS	*6.10 FS
21	1		*UNBEKANNT BUMPER LOWER SPOILER	Not Necessary	273.69 FS	*- FS
22	1		*UNBEKANNT REINFORCEMENT	Not Necessary	625.49 FS	*- FS
23	1		*UNBEKANNT BUMPER CTR BRACKET	Not Necessary	84.22 FS	*- FS
24	1		*UNBEKANNT LHR BUMPER BRACKET (UPPER)	Not Necessary	65.94 FS	*- FS
25	1		*UNBEKANNT RHR BUMPER BRACKET (UPPER)	Not Necessary	65.94 FS	*- FS
26	1		*UNBEKANNT LHR BUMPER BRACKET (SIDE)	Not Necessary	48.60 FS	*- FS
27	1		*GUIDE PROFILE RHS RHR BUMPER BRACKET (SIDE)	Not Necessary	48.60 FS	*- FS
28	1		*REFLECTOR RHS	Not Necessary	61.29 FS	*- FS
29	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
30	1		*SOLAR FILM	Necessary	400.00 FS	*400.00 FS
31	1		*3RD BRAKELIGHT STRIP	Necessary	21.58 FS	*21.58 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					9,945.35	8,268.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	R&R ROOFLINING TO R&R BOOT LID HINGE	New	2,520.00	1,260.00
4	LABOUR	New	4,200.00	1,680.00
5	SPRAY PAINT	New	3,200.00	1,600.00
6	R&R REAR W/SCREEN	New	840.00	840.00
7	TRANSFER BOOT LID MECHANISM	New	840.00	420.00
8	REAR WATER LEAK TEST	New	150.00	150.00
Gross Labour Cost (S\$)			12,510.00	6,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >