

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI23000562/RQY3Q2**Date:** 03/07/2023**REFERENCE**

Insured/Claimant:	TEO KIAN SENG	Policy No:	DMPG23000269	Claim No:	CDMPG23000102
Date of Loss:	13/01/2023	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP26Z		Engine No:	27682431038647
Make & Model:	MERCEDES-BENZ S320L, 3.0 (A)		Chassis No:	WDD2221622A484741
Reg. Date:	13/01/2020 (Man. Year: 2019)		Odometer:	65168 km
Colour:	Brown			
Engine Capacity:	2996 cc			
Market Value/New Car Price:	S\$318,000.00			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R19	Rear Tyre Size:	245/45 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,406.91	8,238.41	168.50	2.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,510.00	7,530.00	2,980.00	28.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,916.91	15,768.41	3,148.50	16.64
- Excess (\$\$)	1,000.00	1,000.00	0.00	0.00
(\$\$)	17,916.91	14,768.41	3,148.50	17.57
+ GST 8.00/8.00% (\$\$)	1,433.35	1,181.47	251.88	17.57
Nett Amount (\$\$)	19,350.26	15,949.88	3,400.38	17.57

INSPECTION

Date of Assignment:	17/01/2023	
Date Inspected:	17/01/2023 Inspected At:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jul 2023)
Parts:	143	MERCEDES-BENZ S320L 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP26Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH/MIRROR FRAME	Broken	1,153.27 FS	*1,153.27 FS
2	1		*RH/MIRROR BOWL	Scratched	197.31 FS	*197.31 FS
3	1		*RH/ADD ,TURN SIGNAL LAMP	Scratched	199.02 FS	*199.02 FS
4	1		*RH/FRONT DOOR	Bent	3,644.02 FS	*3,644.02 FS
5	1		*RH/FRONT DOOR SEAL	Necessary	317.72 FS	*317.72 FS
6	3		*RH/FRONT DOOR DOWEL	Necessary	13.20 FS	*13.20 FS
7	1		*RH/ FRONT DOOR TRIM STRIP	Necessary	342.41 FS	*342.41 FS
8	2		*RH/FRONT DOOR TOP SELF-ADHESIVE TRIM	Necessary	20.74 FS	*20.74 FS
9	2		*RH/ FRONT DOOR BOTTOM SELE-ADHESIVE TRIM	Necessary	50.26 FS	*50.26 FS
10	1		*RH /FRONT FENDER	Buckled	1,365.00 FS	*1,365.00 FS
11	1		*RH /FRONT FENDER TRIM MOULDING	Necessary	93.93 FS	*93.93 FS
12	1		*RH/FRONT DOOR TRIM MOULDING	Necessary	196.65 FS	*196.65 FS
13	1		*RH /REAR DOOR TRIM MOULDING	Not Necessary	168.50 FS	*- FS
14	1		*RH/FRONT WINDOW GUIDE RAIL	Necessary	231.52 FS	*231.52 FS
15	1		*RH/ FRONT DOOR SEALING FRAME	Necessary	57.05 FS	*57.05 FS
16	3		*COMBINATION NUT	Necessary	15.27 FS	*15.27 FS
17	1		*RH /FRONT COVER ,WHEEL ARCH	Torn	263.25 FS	*263.25 FS
18	1		*MOUNTING RAIL	Necessary	15.39 FS	*15.39 FS
19	1		*MOUNTING CLIP	Necessary	9.64 FS	*9.64 FS
20	4		*TRIM CLIP	Necessary	52.76 FS	*52.76 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)

8,406.91

8,238.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING TO REPAIR AFFECTED AREAS ,REMOVE AND REPLACE WITH NEW BODY PANELS AND REFINISH	New	3,840.00	2,880.00
2	RESPRAY FRONT BUMPER & RH/FRONT FENDER & RH/FRONT DOOR & RH/REAR DOOR RH/SIDE MIRROR COVER	New	3,600.00	2,580.00
3	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	480.00	480.00
4	TO REMOVE ,REPLACE HEADLAMP WITH FOCUS	New	120.00	120.00
5	PLACE VEHICLE ON -TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT	New	1,000.00	0.00
6	REMOVE & TRANSFER DOOR MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR	New	600.00	600.00
7	TO INSPECT & CONDUCT WHEEL ALIGNMENT	New	540.00	540.00
8	CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM	New	180.00	180.00
9	ACCIDENT TOWING FROM 87 ZION ROAD TO PLSC	New	150.00	150.00
Gross Labour Cost (\$\$)			10,510.00	7,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >