

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23000575/SPA3Q2**Date:** 06/06/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2000483962
Claimant Vehicle No :	FBD711L	Insured Vehicle No :	SNE7360Y
Date of Loss:	21/12/2022	Nature of Claim:	TP
		Claim No:	202222009042

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBD711L	Engine No:	5YP300471
Make & Model:	YAMAHA T135, 135cc	Chassis No:	5YP300471
Reg. Date:	03/10/2008 (Man. Year: 2008)	Odometer:	507566 km
Colour:	Black		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/80-17	Rear Tyre Size:	70/80-17
Front Left Side:	Maxxis 4 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,695.00	3,754.00	1,941.00	34.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	730.00	520.00	41.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,945.00	4,484.00	2,461.00	35.44
Approved Total (Overridden) (S\$)		3,450.00		
(S\$)	6,945.00	3,450.00	3,495.00	50.32
+ GST 8.00/8.00% (S\$)	555.60	276.00	279.60	50.32
Nett Amount (S\$)	7,500.60	3,726.00	3,774.60	50.32
+ Loss of Use (5.0 x S\$20.00/day) (S\$)		100.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		3,852.75		

INSPECTION

Date of Assignment:	17/01/2023		
Date Inspected:	19/01/2023	Inspected At:	Kivile Enterprise (HQ) BLK 3007 UBI RD 1 #01-408 Singapore 408701
Estimated Period of Repair:	3.0 days		

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Jun 2023)	
Parts:	N/A	YAMAHA T135 135cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBD711L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLEBAR	Dented	105.00 F	*105.00 FL
2	1		*HANDLEBAR HOLDER	Dented	65.00 F	*65.00 FL
3	1		*MIRROR	Scratched	85.00 F	*70.00 FL
4	1		*BALANCER	Scratched	45.00 F	*45.00 FL
5	1		*CLUTCH LEVER	Not Necessary	75.00 F	*- FL
6	1		*BRAKE LEVER	Scratched	75.00 F	*75.00 FL
7	1		*SET COVER	Broken off	600.00 F	*250.00 FL
8	1		*FRONT SIGNAL LH	Broken	65.00 F	*50.00 FL
9	1		*SET FORK	Dented	280.00 F	*280.00 FL
10	1		*FORK LOWER CLAMP	Dented	280.00 F	*120.00 FL
11	1		*STEERING CONE	Dented	110.00 F	*55.00 FL
12	1		*RIM	Dented	480.00 F	*480.00 FL
13	1		*DISC	Dented	160.00 F	*90.00 FL
14	1		*WHEELSHAFT	Dented	135.00 F	*60.00 FL
15	1		*RADIATOR	Scratched	280.00 F	*280.00 FL
16	1		*COOLANT PUMP	Broken	280.00 F	*80.00 FL
17	1		*COOLANT HOSE	Cut	45.00 F	*30.00 FL
18	1		*COOLANT RESERVOIR	Broken	90.00 F	*60.00 FL
19	1		*GEAR PEDAL	Broken	75.00 F	*50.00 FL
20	1		*FRONT FOOTREST	Broken	85.00 F	*85.00 FL
21	1		*FOOTREST RUBBER	Broken	65.00 F	*20.00 FL
22	1		*SIDE STAND	Scratched	110.00 F	*80.00 FL
23	1		*ENGINE COVER LH	Scratched	180.00 F	*90.00 FL
24	1		*BRAKE PEDAL	Scratched	60.00 F	*60.00 FL
25	1		*EXHAUST PIPE YOSHI	Scratched	1,280.00 F	*1,280.00 FL
26	1		*FRONT BASKET	Dented	75.00 F	*50.00 FL
27	1		*FRONT GARNISH	Necessary	75.00 F	*40.00 FL
28	1		*CENTER FAIRING	Broken	125.00 F	*60.00 FL
29	1		*REAR BOX	Scratched	280.00 F	*150.00 FL
30	1		*FRONT NUMBER PLATE	Missing	30.00 FS	*10.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					5,695.00	4,170.00
- List Item Discount on L Items 0.00/10.00% (\$\$)					0.00	416.00
Total Parts (\$\$)					5,695.00	3,754.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODY FRAME REPAIR	New	380.00	300.00
2	PAINTWORK	New	220.00	0.00
3	LABOUR	New	600.00	400.00
4	TOWING	New	50.00	30.00
Gross Labour Cost (\$\$)			1,250.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >