5/17/23, 3:19 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III23000580/RYA3Q2

17/05/2023 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0006372_02

Claimant Vehicle SNE718X Insured Vehicle No: SHD2069Z

No:

Date of Loss: 10/01/2023 Nature of Claim: Claim No: MFL2023D0000356

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNE718X**

Make & Model: 36746583B38A15A BMW 116I, 1.5 (A) Engine No: Reg. Date: 30/11/2021 (Man. Year: 2021) Chassis No: WBA7K120707K24334

Colour: Odometer: 14249 km Grey

Engine Capacity: 1499 cc Market Value/New Car

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 225/45 R17 Rear Tyre Size: Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,130.85	909.80	221.05	19.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,000.00	1,850.00	64.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,980.85	1,909.80	2,071.05	52.03
+ GST 8.00/8.00% (S\$)	318.47	152.78	165.69	52.03
Nett Amount (S\$)	4,299.32	2,062.58	2,236.74	52.03
+ Car Rental (2	2.0 x S\$100.00/day) (S\$)	200.00		

Nett Liability (S\$)

INSPECTION

Date Inspected:

Date of Assignment: 16/01/2023

Performance Motors Limited (Alexandra)

303 Alexandra Road, Sime Darby Performance 17/01/2023 Inspected At:

2,262.58

Centre

Singapore 159941

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL Manager: Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

5/17/23, 3:19 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Apr 2023)

Parts: 144 BMW 116I 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNE718X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty F	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	40.00 FS	*40.00 FS
2	1		*FRONT EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
3	10		*C CLIP FOR PLASTIC NUT	Not Necessary	11.00 FS	*-FS
4	1		*LH SIDE TRIM GRILLE (LUXURY)	Not Necessary	96.95 FS	*-FS
5	1		*LH GRID LATERAL (LUXURY/SPORT)	Not Necessary	113.10 FS	*-FS
6	1		*SUPPORT NUMBER PLATE ECE	Deformed	76.75 FS	*76.75 FS
7	1		*FRT GRILLE (LUXURY)	Cut	710.05 FS	*710.05 FS
F=Fra	nchise pa	art. S=SpcNe	ett.	_		
				Total Parts (S\$)	1,130.85	909.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REPLACE FRONT GRILLE AND ATTACHMENTS	New	2,550.00	850.00
2	TO STICKER WRAPPING FRONT GRILLE AND LHS GRATE TRIM	New	300.00	150.00
	Gross Labo	our Cost (S\$)	2,850.00	1,000.00
	Report was unsubmitted during th	s print-out.		

< END OF ESTIMATES >