

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23000597/NPA3Q2**Date:** 30/03/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP0001079351
Claimant Vehicle No :	SHD1694A	Insured Vehicle No :	GBL9836J
Date of Loss:	12/01/2023	Nature of Claim:	TP
		Claim No:	202332004564

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD1694A	Engine No:	G4LELU040537
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)	Chassis No:	KMHC851CVLU240853
Reg. Date:	22/03/2021 (Man. Year: 2020)	Odometer:	146787 km
Colour:	Silver		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Hankook 4 mm	Rear Left Side:	Hankook 4 mm
Front Right Side:	Hankook 4 mm	Rear Right Side:	Hankook 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	827.92	777.92	50.00	6.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,030.00	2,150.00	880.00	29.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,857.92	2,927.92	930.00	24.11
+ GST 8.00/8.00% (S\$)	308.63	234.23	74.40	24.11
Nett Amount (S\$)	4,166.55	3,162.15	1,004.40	24.11
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$85.32/day) (S\$)		255.96		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,570.11		
Global Sum Settlement (S\$)		3,570.00		

INSPECTION

Date of Assignment:	13/01/2023		
Date Inspected:	31/01/2023	Inspected At:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #04-03 Singapore 486443
Estimated Period of Repair:	5.0 days		

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2023)
Parts: 143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD1694A)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S DOOR PROTECTOR	Scratched	38.00 FL	*38.00 FL
2	1		*REAR N/S DOOR PROTECTOR	Scratched	38.00 FL	*38.00 FL
3	1		*N/S ROCKER PANEL GARNISH	Deformed	290.00 FL	*290.00 FL
4	1		*WHEEL COVER	Scratched	346.40 FL	*346.40 FL
5	1		*SET N/S DOOR STICKER	Necessary	100.00 FS	*100.00 FS
6	1		*REAR O/S FENDER STICKER	Necessary	60.00 FS	*60.00 FS
7	1		*SET N/S ROCKER PANEL GARNISH CLIPS	Necessary	48.00 FS	*48.00 FS
8	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	970.40	920.40
- List Item Discount on L Items 20.00/20.00% (\$)	142.48	142.48
Total Parts (\$)	827.92	777.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WHEEL ALIGNMENT	New	80.00	0.00
2	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING TO KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE OF THE FRONT N/S FENDER ,FRONT N/S DOOR ,REAR N/S DOOR ,REAR N/S FENDER ,REAR BUMPER	New	1,200.00	900.00
3	TO PUTTY AND SPRAY PAINTING ON THE FRONT N/S FENDER ,FRONT N/S DOOR ,REAR N/S DOOR ,REAR N/S FENDER ,N/S ROCKER PANEL GARNISH , REAR BUMPER ,FRONT N/S & O/S DOOR PROTECTOR (SILVER)	New	1,600.00	1,200.00
4	TO APPLY RUSTPROOFING ON REPAIRED PANELS	New	150.00	50.00
Gross Labour Cost (\$\$)			3,030.00	2,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >