

(08/11/13) WEI

ASS. REC. PY: Paul

REF:

CS/ABS 23000598/R9y3

C
3180**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: ABC9945Aat Workshop m/s SNH AH TEGof 3 Pioneer R NORTH HUI-18Insured: AIS

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: 600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 20K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: ABC9945AYr Regn: 2014 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN CABSTAR 3.0 SMT c.c 2953Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 341042 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNISC2P2420855475Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195R15CR: 165R13C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front

Rear

R/Bal. 7 mmR/Bal. 5/5 mmL/Bal. 7 mmL/Bal. 5/5 mmD.O.A. 07/01/23D.O.I. 18/01/23Survey held at SNH AH TEGDes. of Damages: FR / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 19K

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format : _____

Lump Sum / I.E.I. (\$) _____

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg;darren@sngahtee.com;janice@sngahtee.com

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2001163748-01	Date of Loss:	07/01/2023
Vehicle Reg. No.:	GBC9945A	Driveable?	
Driver Age/Info:	47 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	MULTI WAYS EQUIPMENT PTE. LTD.	Contact No:	+6598215748
Driver:	RIPON MOHAMMED		
Make/Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Vehicle Reg. Date:	31/03/2014
Vehicle Colour:	SILVER	Chassis No:	JN1SC2F24Z0855425
Engine No:	ZD30334670K		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	25		
Description of Accident/Loss	REFER TO POLICE REPORT		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	23,372.00
Miscellaneous Items	0.00
Labour	4,900.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	28,272.00
+ GST 8.00% (S\$)	2,261.76
Nett Amount (S\$)	30,533.76

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 18 Jan 2023)

Parts: N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/GBC9945A/18/01/2023 14:24

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE <i>lt</i>	0	0.00	*25.00 FS
2	1		*FRT BUMPER <i>de</i>	0.00	0.00	*450.00 F
3	1		*FRT GRILLE ASSY <i>ca</i>	0.00	0.00	*260.00 F
4	1		*FRT GRILLE EMBLEM <i>acc</i>	0.00	0.00	*60.00 F
5	10		*FRT GRILLE CLIPS (+) <i>acc</i>	0.00	0.00	*50.00 F
6	10		*FRT GRILLE CLIPS (-) <i>acc</i>	0.00	0.00	*50.00 F
7	1		*FRT PANEL ASSY <i>lt</i>	0.00	0.00	*650.00 F
8	1		*FRT PANEL CABSTAR STICKER <i>acc</i>	0.00	0.00	*45.00 F
9	2		*FRT CORNER PANEL LH/RH <i>lt</i>	0.00	0.00	*460.00 F
10	2		*FRT UPP CORNER PANEL LH/RH <i>ca</i>	0.00	0.00	*180.00 F
11	2		*FRT UPP CORNER PROTECTOR LH/RH <i>MU</i>	0.00	0.00	*40.00 F
12	1		*FRT WIPER PANEL <i>lt</i>	0.00	0.00	*300.00 F
13	2		*FRT WIPER ARM LH/RH <i>X</i>	0.00	0.00	*140.00 F
14	2		*FRT WIPER BLADE LH/RH <i>X</i>	0.00	0.00	*30.00 F
15	1		*FRT WIPER LINGKAGE	0.00	0.00	*90.00 F
16	2		*FRT HEADLAMP LH/RH <i>lt</i>	0.00	0.00	*500.00 F
17	2		*FRT HEADLAMP LOWER APRON LH/RH <i>lt</i>	0.00	0.00	*120.00 F
18	1		*FRT SIDE MIRROR ARM LH <i>lt</i>	0.00	0.00	*120.00 F
19	1		*FRT SIDE MIRROR RETANGULAR LH <i>ca</i>	0.00	0.00	*120.00 F
20	1		*FRT SIDE MIRROR ROUND LH <i>ca</i>	0.00	0.00	*50.00 F
21	1		*FRT SIDE MIRROR ROUND COVER LH <i>X</i>	0.00	0.00	*20.00 F
22	1		*FRT SIDE MIRROR ARM RH <i>mir</i>	0.00	0.00	*120.00 F
23	1		*FRT SIDE MIRROR RETANGULAR RH <i>mis</i>	0.00	0.00	*120.00 F
24	1		*FRT DOOR RH <i>acc</i>	0.00	0.00	*700.00 F
25	1		*FRT DOOR UPP HINGE RH <i>lt</i>	0.00	0.00	*50.00 F
26	1		*FRT DOOR LWR HINGE RH <i>lt</i>	0.00	0.00	*50.00 F
27	1		*FRT DOOR RUBBER RH <i>acc</i>	0.00	0.00	*75.00 F
28	1		*FRT DOOR LOCK RH <i>lt</i>	0.00	0.00	*120.00 F
29	1		*FRT DOOR OUTER HANDLE RH <i>X</i>	0.00	0.00	*120.00 F
30	1		*FRT DOOR INNER HANDLE RH <i>ca</i>	0.00	0.00	*35.00 F
31	1		*FRT DOOR GARNISH @FRT RH <i>mis</i>	0.00	0.00	*30.00 F
32	1		*FRT DOOR GLASS RH <i>lt</i>	0.00	0.00	*300.00 F
33	1		*FRT DOOR GLASS REGULATOR RH	0.00	0.00	*90.00 F
34	1		*FRT DOOR GLASS MOTOR RH	0.00	0.00	*280.00 F
35	1		*FRT DOOR GLASS INNER MOULDING RH <i>de</i>	0.00	0.00	*45.00 F
36	1		*FRT DOOR GLASS OUTER MOULDING RH <i>de</i>	0.00	0.00	*65.00 F
37	1		*FRT DOOR GLASS CHANNEL RH	0.00	0.00	*115.00 F
38	1		*FRT DOOR FRAME INNER TRIM RH <i>X</i>	0.00	0.00	*80.00 F
39	1		*FRT DOOR GLASS SWITCH RH <i>ca</i>	0.00	0.00	*110.00 F
40	1		*FRT DOOR SIDE SIGNAL LAMP RH <i>X</i>	0.00	0.00	*30.00 F
41	1		*FRT DOOR INNER TRIM BOARD RH <i>de</i>	0.00	0.00	*300.00 F
42	1		*FRT DOOR UPP HANDLE RH <i>de</i>	0.00	0.00	*110.00 F
43	1		*FRT STEP PANEL RH <i>ca</i>	0.00	0.00	*100.00 F
44	1		*FRT STEP GARNISH RH <i>ca</i>	0.00	0.00	*90.00 F
45	1		*FRT ROCKER PANEL RH <i>lt</i>	0.00	0.00	*430.00 F

Sng Ah Tee Motor & Panel Service Pte Ltd/GBC9945A/18/01/2023 14:24. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*FRT SCUFF PLATE RH <i>cm</i>	0.00	0.00	*60.00 F
47	1		*FRT WINDSCREEN <i>bw</i>	0.00	0.00	*550.00 F
48	1		*FRT WINDSCREEN MOULDING <i>ac</i>	0.00	0.00	*90.00 F
49	1		*FRT DASHBOARD <i>cm</i>	0.00	0.00	*1,000.00 F
50	1		*FRT DASHBOARD SUPPORT BEAM <i>?</i>	0.00	0.00	*500.00 F
51	1		*FRT WASHER TANK <i>cm</i>	0.00	0.00	*80.00 F
52	1		*FRT CHASSIS CROSSMEMBER <i>bt</i>	0.00	0.00	*950.00 F
53	1		*FRT STEERING COLUMN <i>?</i>	0.00	0.00	*1,000.00 F
54	1		*FRT STEERING COLUMN COVER <i>?</i>	0.00	0.00	*100.00 F
55	1		*FRT STEERING COLUMN DUCT COVER <i>?</i>	0.00	0.00	*100.00 F
56	1		*FRT STEERING COLUMN LOWER COVER <i>?</i>	0.00	0.00	*30.00 F
57	1		*FRT STEERING GEAR ASSY <i>?</i>	0.00	0.00	*550.00 F
			STERING BOX			
58	1		*AIRCON BLOWER <i>?</i>	0.00	0.00	*450.00 F
59	1		*HEATER BLOWER <i>?</i>	0.00	0.00	*1,000.00 F
60	1		*FRT PILLAR INNER RH <i>bt</i>	0.00	0.00	*900.00 F
			FRT PILLAR OUTER RH			
61	2		*FRT PILLAR INNER TRIM L/RH <i>cm/lpc</i>	0.00	0.00	*400.00 F
62	1		*FRT ACCELERATE PEDAL <i>?</i>	0.00	0.00	*100.00 F
63	1		*FRT BRAKE PEDAL <i>?</i>	0.00	0.00	*100.00 F
64	1		*FRT BRAKE BOOSTER <i>?</i>	0.00	0.00	*950.00 F
65	1		*FRT TYRE RH <i>X</i>	0	0.00	*280.00 FS
66	1		*FRT TYRE RIMS RH <i>X</i>	0	0.00	*180.00 FS
67	1		*FRT ABSORBER RH <i>?</i>	0.00	0.00	*100.00 F
68	1		*FRT UPPER CONTROL ARM RH <i>?</i>	0.00	0.00	*280.00 F
69	1		*FRT LOWER CONTROL ARM RH <i>?</i>	0.00	0.00	*260.00 F
70	1		*FRT WHEEL HUB & BEARING RH <i>?</i>	0.00	0.00	*450.00 F
71	1		*FRT KNUCKLE ARM RH <i>?</i>	0.00	0.00	*550.00 F
72	1		*FRT SUBFRAME <i>?</i>	0.00	0.00	*950.00 F
73	1		*FRT WINDSCREEN SEALANT <i>ac</i>	0	0.00	*40.00 FS
74	1		*FRT ERP BRACKET <i>ac</i>	0	0.00	*26.00 FS
75	2		*ROC STICKER <i>ac</i>	0	0.00	*40.00 FS
76	1		*FRT CABIN SUPPORT BEAM <i>?</i>	0.00	0.00	*500.00 F
77	2		*FRT CABIN SUPP BRACKET LH/RH <i>?</i>	0.00	0.00	*280.00 F
78	2		*FRT CABIN SUPP BUSH LH/RH <i>?</i>	0.00	0.00	*80.00 F
79	1		*FRT STEERING RACK <i>?</i>	0.00	0.00	*1,050.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$) 21,301.00
+ Margin on L,N Items 10.00% (S\$) 2,071.00

Total Parts (S\$) 23,372.00

Sng Ah Tee Motor & Panel Service Pte Ltd/GBC9945A/18/01/2023 14:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

* There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK FRT PILLAR LH,FRT DOOR LH,FRT DOOR RR PANEL LH,RR CABIN PANEL,FRT PANEL,WELD,REMOVE & REPLACE ABOVE PARTS	New	1400 1,600.00
2	TO PUTTY ,RESRPAY AND PAINTING ON AFFECTED AREAS	New	1400 1,600.00
3	TO CHECK WIRING	New	30.00 ✓
4	TO TRANSFER FRT DOOR GLASS RH	New	60.00 ✓
5	TO REMOVE & REFIX FRT WINDSCREEN	New	120.00 ✓
6	TO APPLY WHEEL ALIGNMENT	New	60 80.00
7	TO STRAIGHTEN FRT CHASSIS	New	250 350.00
8	TO REMOVE & REFIX FRT DASHBOARD	New	150 180.00
9	TO REMOVE & REFIX FRT UNDERCARRIAGE	New	200 250.00
10	TO LIFT UP FRT CABIN <i>photo</i>	New	250 350.00
11	TO TOP UP AIRCON GAS	New	? 100.00
12	TO DIAGNOSE AND RESET FAULT CODE	New	100 180.00
Gross Labour Cost (S\$)			4,900.00

Sng Ah Tee Motor & Panel Service Pte Ltd/GBC9945A/18/01/2023 14:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Panel
Hf 500100 68
10
4/S
18/01/23 @ 1600
EXCESS: 600
Reuter
Resing after repair

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	318D

Vehicle Details

Vehicle No.:	GBC9945A
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Feb 2023
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	ZD30334670K
Chassis No.:	JN1SC2F24Z0855425
Maximum Power Output:	-
Open Market Value:	\$25,592.00
Original Registration Date:	31 Mar 2014
First Registration Date:	31 Mar 2014
Transfer Count:	0
Actual ARF Paid:	\$1,280.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	30 Mar 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$7,504.00
COE Rebate Amount:	\$823.00
Total Rebate Amount:	\$823.00

The information contained herein is correct as at 10 Jan 2023

OK

Nissan Cabstar

Overview

Financial

Accessories

Similar

Research

Photos

Map

ABWIN 論輝

YOUR FIRST CHOICE AUTOMOTIVE SERVICE PROVIDER



Price	\$18,800	Lifespan ?	04-Feb-2034
Depreciation ?	\$18,010 /yr View models with similar depre	Reg Date	05-Feb-2014 (1yr 16days COE left)
Mileage	N.A.	Manufactured ?	2013
Road Tax ?	N.A.	Transmission	Manual
Dereg Value ?	\$3,410 as of today (change)	Fuel Type	Diesel
COE ?	\$32,670	OMV ?	\$25,592
Engine Cap	2,953 cc	ARF ?	\$1,280
Curb Weight ?	1,800 kg	No. of Owners ?	2