

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

AUTO & GENERAL INSURANCE (S) PL Ref: CS3/AGI23000606/Uqy3m4

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Codo: AGI

Date:

13/02/2023

			Code:	AGI		
1. Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	SGP 8335P	Veh. Inspected	FBB 4951U		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	C10019915/KY	Excess (\$)	0.00		
	Assign From	MAYBIE CHUA	Assign Date	18/01/2023		
2. Vehicle Particulars & Condition						
	Make & Model	HONDA CB400 M	c.c	399		
	Engine No.	HIDDEN	Year of Reg.	2007		
	Chassis No.	NC391204720	Colour	SILVER		
	Odometer	245488 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	GOOD				
3. Conditions of Tyres						
		Size	Make	Balance		
	R/H Front Tyre	120/60 ZR17	BRIDGESTONE	7 mm		
	L/H Front Tyre			mm		
	R/H Rear Tyre	160/60 ZR17	BRIDGESTONE	7 mm		
	L/H Rear Tyre			mm		
4. Description of Damages						

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

5.	General Information					
	Accident Date	12/01/2023	Inspect Date / Time	18/01/2023 (12:35 PM)		
	Survey held at	HOTGEARZSG				
		13 KAKI BUKIT ROAD 4, #01-16, BARTLEY BIZ CENTRE, SINGAPORE 417807				

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:

Report Ref No. CS3/AGI23000606/Uqy3m4

Inspected By

CHUA KANG SENG

K.K.LAU CPT(RET)

Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

4 Working Days