

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000607/AWP3E2**Date:** 13/03/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNW00015252207

**Claimant Vehicle
No :** SJR2954X**Insured Vehicle
No :** SKV4126Z

Date of Loss: 13/01/2023

Nature of Claim: TP

Claim
No: SNM23D200449/C02/LEWLCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJR2954X**

Make & Model: KIA CERATO, 1.6 (A)

Engine No: G4FC9H263096

Reg. Date: 18/06/2009 (Man. Year: 2009)

Chassis No: KNAFH221395085821

Colour: Blue

Odometer: 182701 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,082.59	5,276.57	2,806.02	34.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	2,220.00	1,330.00	37.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,632.59	7,496.57	4,136.02	35.56
Approved Total (Overridden) (S\$)		6,000.00		
Nett Amount (S\$)	11,632.59	6,000.00	5,632.59	48.42

INSPECTION

Date of Assignment: 18/01/2023

Date Inspected: 17/01/2023 Inspected At:

Hua Meng Spray Painting Workshop (HQ)
No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2023)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR2954X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Buckled	981.70 FL	*793.00 FL
2	2		*REAR BOOTLID HINGE	Not Necessary	167.20 FL	*- FL
3	1		*REAR BOOTLID UPPER LOCK	Damaged	143.90 FL	*143.90 FL
4	1		*REAR BOOTLID LOWER LOCK	Not Necessary	54.50 FL	*- FL
5	1		*REAR BOOTLID INSULATION	Not Necessary	142.20 FL	*- FL
6	1		*REAR BOOTLID WEATHER STRIP	Cut	108.70 FL	*108.70 FL
7	1		*REAR BOOTLID CENTRE LOGO	Necessary	31.70 FL	*31.70 FL
8	1		*REAR BOOTLID CERATO EMBLEM	Necessary	37.70 FL	*37.70 FL
9	1		*REAR BOOTLID FORTE EMBLEM	Necessary	35.90 FL	*35.90 FL
10	1		*REAR BOOTLID HANDLE	Not Necessary	142.80 FL	*- FL
11	2		*REAR BOOTLID REFLECTOR	Cut	611.40 FL	*500.00 FL
12	2		*REAR LAMP	Cut	559.00 FL	*559.00 FL
13	2		*REAR LAMP HOUSING	Buckled	215.20 FL	*215.20 FL
14	1		*REAR END PANEL	Dented	393.00 FL	*393.00 FL
15	1		*REAR END PANEL TOP GARNISH	Deformed	95.00 FL	*95.00 FL
16	1		*REAR BUMPER	Deformed	772.00 FL	*698.00 FL
17	2		*REAR BUMPER SIDE HOLDER	Damaged	78.00 FL	*78.00 FL
18	1		*REAR BUMPER REINFORCEMENT	Distorted	390.20 FL	*390.20 FL
19	1		*REAR BUMPER SPONGE	Cracked	182.60 FL	*182.60 FL
20	2		*REAR BUMPER BRACKET	Bent	88.40 FL	*88.40 FL
21	1		*REAR BUMPER LOWER LIP	Deformed	252.00 FL	*252.00 FL
22	1		*REAR FENDER	Repair	961.20 FL	*- FL
23	2		*REAR FENDER INNER TRIM	Torn	586.80 FL	*510.00 FL
24	1		*REAR SPARE TYRE TOP BOARD	Deformed	295.00 FL	*295.00 FL
25	1		*REAR EXHAUST PIPE	Not Necessary	711.00 FL	*- FL
26	1		*REAR EXHAUST PIPE CHROME	Not Necessary	88.00 FL	*- FL
27	1		*REAR BUMPER REVERSE SENSOR (4PCS)	Damaged (2Pcs Only)	720.00 FS	*380.00 FS
28	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,895.10	5,817.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	812.51	540.73
Total Parts (\$\$)	8,082.59	5,276.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY REAR END PANEL SEALANT	New	50.00	50.00
2	REMOVE & REFIX BOOTLID INNER GARNISH	New	200.00	60.00
3	REMOVE & REFIX REVERSE SENSOR	New	150.00	50.00
4	REMOVE & REFIX EXHAUST PIPE	New	200.00	0.00
5	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,600.00	1,000.00
6	RESPRAY PAINTING	New	1,200.00	1,000.00
7	TUFF KOTE	New	150.00	60.00
Gross Labour Cost (\$)			3,550.00	2,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >