

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000615/UWP3Q2**Date:** 20/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00108212200		
Claimant Vehicle No :	GBK734J	Insured Vehicle No :	YM9258A		
Date of Loss:	14/01/2023	Nature of Claim:	TP	Claim No:	SNM23D200447/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK734J	Engine No:	QR20996910Q
Make & Model:	NISSAN CABSTAR, 2.0 SINGLE CAB (M)	Chassis No:	JN1SA2F24Z0000088
Reg. Date:	29/11/2019 (Man. Year: 2019)	Odometer:	88540 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R13 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Yokohama 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Yokohama 6/6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,527.47	3,678.47	5,849.00	61.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	1,330.00	2,710.00	67.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,567.47	5,008.47	8,559.00	63.08
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	13,567.47	4,000.00	9,567.47	70.52
+ GST 8.00/8.00% (S\$)	1,085.40	320.00	765.40	70.52
Nett Amount (S\$)	14,652.87	4,320.00	10,332.87	70.52

INSPECTION

Date of Assignment:	30/01/2023	
Date Inspected:	06/02/2023 Inspected At:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Feb 2023)	
Parts:	N/A	NISSAN CABSTAR 2.0 SINGLE CAB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK734J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,688.20 FN	*1,688.20 FN
2	2		*REAR TAILGATE LOCK LATCHS	Repair	760.00 FN	*- FN
3	2		*REAR TAILGATE LOCK LOWER L BRACKETS	Repair	360.00 FN	*- FN
4	2		*REAR TAILGATE LOCK LOWER L BRACKET RUBBERS	Not Necessary	160.00 FN	*- FN
5	1		*REAR TAILGATE NISSAN STICKER	Necessary	80.00 FN	*80.00 FN
6	2		*TAILLAMPS	Cracked	490.00 FN	*490.00 FN
7	2		*TAILLAMP HOUSING PANELS	Not Necessary	360.00 FN	*- FN
8	1		*REAR LICENCE PLATE BRACKET	Bent	155.00 FN	*155.00 FN
9	1		*REAR END PANEL	Bent	685.10 FN	*685.10 FN
10	1		*REAR SPARE TYRE CARRIER & CHAIN	Not Necessary	290.00 FN	*- FN
11	1		*DROPSIDE GATE PANEL N/S	Repair	1,890.00 FN	*- FN
12	1		*DROPSIDE GATE PANEL O/S	Repair	1,890.00 FN	*- FN
13	1		*SET REAR TAILGATE 70KM/H & 13 PAX STICKER	Necessary	50.00 FS	*20.00 FS
14	1		*SET REAR REVERSE SENSOR	Cracked	300.00 FS	*200.00 FS
15	1		*REAR LICENCE PLATE	Bent	50.00 FS	*20.00 FS
16	1		*REAR ALUMINIUM PLATE	Bent	800.00 FS	*600.00 FS
17	1		*SET REAR ALUMINIUM PLATE RIVET	Necessary	100.00 FS	*50.00 FS
18	1		*REAR STEP BRACKET	Repair	300.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	10,408.30	3,988.30
- Nett Item Discount on N Items 10.00/10.00% (S\$)	880.83	309.83
Total Parts (S\$)	9,527.47	3,678.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	100.00	50.00
3	TO DISMANTLE & REPLACED REAR CARGO DECK	New	800.00	0.00
4	TO SPRAY RUST PROOFING	New	90.00	60.00
5	LABOUR FOR PANEL BEATING & RPELACED PARTS	New	1,200.00	700.00
6	TO PUTTY & SPRAY PAINTING	New	1,800.00	500.00
Gross Labour Cost (S\$)			4,040.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >