2/20/23, 9:32 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIS23000618/KQY3Q2

20/02/2023 Date:

REFERENCE

No:

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No:

Claimant Vehicle

SLS1627T

Insured Vehicle No:

SGC18B

Date of Loss: 14/01/2023 Nature of Claim: TΡ

Claim No: 2023 32004578KC

Yes

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS1627T**

TOYOTA C-HR, 1.8 (A) Make & Model: Engine No: 2ZR8125208 Reg. Date: 11/09/2017 (Man. Year: 2017) Chassis No: ZYX102046049 Colour: Metallic Pearl White Odometer: 457753 km

Engine Capacity: 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

215/60 R17 215/60 R17 Front Tyre Size: Rear Tyre Size: Front Left Side: Arivo 7 mm Rear Left Side: Arivo 7 mm Front Right Side: Rear Right Side: Arivo 7 mm Arivo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,878.02	1,346.22	1,531.80	53.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,220.00	430.00	790.00	64.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S	\$) 4,098.02	1,776.22	2,321.80	56.66
Approved Total (Overridden) (S	\$)	1,400.00		
Nett Amount (S	\$) 4,098.02	1,400.00	2,698.02	65.84
Global	Sum Settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 18/01/2023

Lian Her Motors (Ang Mo Kio)

Date Inspected: 14/02/2023 Inspected At: Blk 5038, Ang Mo Kio Industrial Park 2, #01-405

Singapore 569541

Estimated Period of Repair: 2.0 days

Adjuster: **KENNETH KONG** Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

2/20/23, 9:32 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Feb 2023)

Parts: M1-SUV TOYOTA C-HR 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLS1627T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	855.60 FL	*545.10 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	483.20 FL	*455.70 FL
3	2		*REAR O/S BUMPER REFLECTOR GARNISH	Serviceable	251.20 FL	*- FL
4	1		*REAR LOWER BUMPER	Cracked	487.50 FL	*487.50 FL
5	2		*REAR BUMPER SIDE RETAINER	Serviceable	150.20 FL	*- FL
6	1		*REAR O/S FENDER ARCH GARNISH	Serviceable	175.20 FL	*- FL
7	1		*REAR END PANEL	Repair	725.70 FL	*- FL
8	1		*REAR END PANEL INNER GARNISH	Serviceable	402.10 FL	*- FL
9	15		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
10	1		*REAR REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
F=Fra	inchise	part. S=SpcN	lett. L=ListItemDisc List Item Discount on L Items 2	Sub Total (S\$) 25.00/25.00% (S\$)	3,760.70 882.68	1,718.30 372.08
				Total Parts (S\$)	2,878.02	1,346.22
			Report was unsubmitted during this pri	int-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount	
Lab	our Items				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING & CUTTING	New	700.00	200.00	
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	500.00	220.00	
3	CHECK AND RECONNECT WIRING	New	20.00	10.00	
	Gross Labour Cost (S\$)		1,220.00	430.00	
	Report was unsubmitted during this print-out.				

< END OF ESTIMATES >