

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT HSBC LIFE (SINGAPORE) PTE LTD Ref: CS3/ASM23000619/Uqp3m4 10 MARINA BOULEVARD #48-01 MARINA BAY Date: 02/03/2023 FINANCIAL CENTRE TOWER 2 SINGAPORE Code: HSB ATTN: KHOR SAW THENG Policy Particulars :- (THIRD PARTY CLAIM) 1. SHD 6723S FQ 6045X Insured Veh. Veh. Inspected VFX/P2419138 0.00 Policy No. Coverage (\$) S2M0498W 0.00 Claim No. Excess (\$) KHOR SAW THENG 18/01/2023 **Assign Date** Assign From Vehicle Particulars & Condition 2. YAMAHA RXZ 133 Make & Model **HIDDEN Engine No.** Year of Reg. 1998 ZMC240432 **BLACK** Chassis No. Colour Odometer 70577 KM **AFFECTED** Steering **IN ORDER** SPORTS RIM Modification **Brakes** FAIR General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre **DUNLOP** 80-90-17 6 mm L/H Front Tyre mm DUNLOP 90-80-17 R/H Rear Tyre 6 mm L/H Rear Tyre mm **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. 5. **General Information** 17/08/2022 Inspect Date / Time 19/01/2023 ( 02:07 PM ) **Accident Date** Survey held at PROSPIN MOTORSPORTS 25 KAKI BUKIT ROAD 4 #03-30 SYNERGY SINGAPORE 417800 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,800-\$4,800 5b. **Estimate Days of Repair** 

Report Ref No. CS3/ASM23000619/Uqp3m4

Inspected By

CHUA KANG SENG

Licensed Appraiser

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

4 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser