

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 1537M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	TO REPAIR SEE LABOUR	773.80	-
1	FRONT BONNET LOCK	NOT NECESSARY	88.90	-
1	FRONT BUMPER	DENTED	531.10	531.10
1	FRONT BUMPER GRILLE	TORN	136.00	136.00
1	FRONT BUMPER TOW COVER	NOT NECESSARY	38.00	-
1	N/S FRONT BUMPER SIDE RETAINER	NECESSARY	98.90	98.90
1	N/S FRONT BUMPER FOG LAMP COVER	NOT NECESSARY	168.00	-
1	FRONT BUMPER SPONGE	TORN	78.60	78.60
1	FRONT BUMPER REINFORCEMENT	DENTED	449.80	449.80
1	FRONT GRILLE WITH LOGO	CRACKED	538.40	538.40
1	BRACE PANEL	TO REPAIR SEE LABOUR	180.80	-
2	FRONT HEADLAMP @\$995.20	N/S NOT NECESSARY / O/S HOLDER CRACKED	1,990.40	995.20
2	FRONT HEADLAMP BRACKET @\$95.60	NOT NECESSARY	191.20	-
	LESS 25% DISCOUNT		-1,315.98	-707.00
			3,947.92	2,121.00
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE WITH HOLDER (SN)	SCRATCHED	50.00	40.00
			50.00	40.00
	LABOUR			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		50.00	20.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT BONNET AND BRACE PANEL.		800.00	400.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		800.00	500.00
			1,650.00	920.00
	GRAND TOTAL		5,647.92	3,081.00

Report Ref No. CS/SPF23000621/Uqy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,450.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/SPF23000621/Uqy3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,450-\$2,800

CHUA KANG SENG

Licensed Appraiser