



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)			Ref:	CS/SPF23000621/Uqy3e2
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1			Date:	03/04/2023
HEMMANT ROADSINGAPORE 438675				
ATTN: HAFIZUL FARHAN			Code:	SPF
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	QX 237G	Veh. Inspected	SMR 1537M	
Policy No.		Coverage (\$)	0.00	
Claim No.	ACS/105/009/2023/001	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	18/01/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA COROLLA AXIO HYBRID (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	NKE1657221344	Colour	GREY	
Odometer	309278 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	MICHELIN	7 mm	
L/H Front Tyre	185/60 R15	MICHELIN	7 mm	
R/H Rear Tyre	185/60 R15	MICHELIN	7 mm	
L/H Rear Tyre	185/60 R15	MICHELIN	7 mm	
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
	DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
Accident Date	15/01/2023	Inspection Date	19/01/2023	
Survey held at	TLM AUTOMOBILE PTE LTD 1 DEFU LANE 6, DEFU INDUSTRIAL PARK A, SINGAPORE 539365			
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	