



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 9044E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LHF DOOR	BENT	980.00	980.00
1	LHF DOOR RUBBER	NOT NECESSARY	220.00	-
1	LHF DOOR GARNISH	CUT	32.60	32.60
1	LH SLIDING DOOR	TO REPAIR SEE LABOUR	689.90	-
1	LHR DOOR RUBBER	CUT	285.00	285.00
1	LH SLIDING DOOR GARNISH	CUT	458.00	458.00
	LESS 10% DISCOUNT		-	-175.56
	COST PLUS 10%		266.55	-
			2,932.05	1,580.04
	<u>SPECIAL NETT ITEMS</u>			
1	ART WORK (SN)	NECESSARY	580.00	200.00
1	COMPANY STICKER (SN)	NECESSARY	30.00	30.00
			610.00	230.00
	<u>LABOUR</u>			
	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA ,TO REMOVE & REFIT DAMAGE PARTS .INCLUSIVE OF THE REPAIR OF LH SLIDING DOOR .		580.00	300.00
	PUTTY & SPRAY PAINTING OF AFFECTED PORTION.		720.00	400.00
	TO TRANSFER LHF DOOR .		180.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	100.00	-
			1,580.00	760.00
	GRAND TOTAL		5,122.05	2,570.04
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,050.00

Report Ref No. CS/AGI23000623/Twy3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.