3/15/23, 4:00 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI23000631/UVP3E2

15/03/2023 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNW00265802100

Claimant Vehicle

XD6020Y

Insured Vehicle No:

SME7329B

Date of Loss:

No:

14/01/2023

Nature of Claim: TP

Claim No:

SNM23D200485/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XD6020Y**

Make & Model: MITSUBISHI FV51JJD4RDEA, 12.9 D (M) **Engine No:** 6M70451891 Chassis No: Reg. Date: 29/08/2012 (Man. Year: 2012) FV51JJA00852 Colour: White/Green Odometer: 340161 km

Engine Capacity: 12882 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 10.00 R20 (D/D) Front Left Side: Rear Left Side: Doupro 6 mm Doupro 7/7/7/7 mm Rear Right Side: Front Right Side: Doupro 6 mm Doupro 7/7/7/7 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|-----------------------------------|------------|------------|------------|--------|
| Parts | | 63,950.00 | 21,480.00 | 42,470.00 | 66.41 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 6,530.00 | 2,300.00 | 4,230.00 | 64.78 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Calculated Gross Total (S\$) | 70,480.00 | 23,780.00 | 46,700.00 | 66.26 |
| | Approved Total (Overridden) (S\$) | | 17,800.00 | | |
| | (S\$) | 70,480.00 | 17,800.00 | 52,680.00 | 74.74 |
| | + GST 8.00/8.00% (S\$) | 5,638.40 | 1,424.00 | 4,214.40 | 74.74 |
| | Nett Amount (S\$) | 76,118.40 | 19,224.00 | 56,894.40 | 74.74 |

INSPECTION

Date of Assignment: 18/01/2023

Mah Lian Motor Vehicle Repairer (HQ) Date Inspected: 31/01/2023 Inspected At: NO. 38 DEFU LANE 9

Singapore 539278

Estimated Period of Repair: 3.0 days

MARCUS CHUA **VERON CHEN** Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 15 Mar 2023)

Parts: N/A MITSUBISHI FV51JJD4RDEA 12.9 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XD6020Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | No. | Particulars | Condition | Repairer's | Amount |
|-------|---------|-----------|--|-----------------------|--------------|--------------|
| 1 | 1 | | *TMA MODULE A ENERGY ABSORBIG BOX | Distorted | 8,980.00 FS | *8,980.00 FS |
| 2 | 1 | | *BOTTOM ANGLE CARTRIDGE, MASH | Distorted | 3,050.00 FS | *1,000.00 FS |
| 3 | 1 | | *TOP ANGLE CARTRIDGE, MASH | Distorted | 3,180.00 FS | *1,000.00 FS |
| 4 | 1 | | *REAR DIAPHRAGM, CARTRIDGE, MASH | No such part | 4,250.00 FS | *-FS |
| 5 | 1 | | *CARTRIDGE TAIL LIGHT ASSY RH | Not Necessary | 580.00 FS | *-FS |
| 6 | 1 | | *CARTRIDGE TAIL LIGHT ASSY LH | Broken | 580.00 FS | *300.00 FS |
| 7 | 1 | | *ICC BAR LIGHT ASSY W/COVER FLAP | Not Necessary | 980.00 FS | *-FS |
| 8 | 1 | | *TMA MODULE C MASH ENERGY ABSORBING BOX | No such part | 9,850.00 FS | *-FS |
| 9 | 1 | | *CARTRIDGE TUBE ASSY LH MASH, VEHICLE REINFORCING BAR | R Warped / Cracked | 15,350.00 FS | *5,000.00 FS |
| 10 | 1 | | *CARTRIDGE TUBE ASSY RH MASH, VEHICLE REINFORCING BAR | Warped / Cracked | 15,350.00 FS | *5,000.00 FS |
| 11 | 1 | | *SET 3M REFLECTIVE STICKERS | Necessary | 1,800.00 FS | *200.00 FS |
| F=Fra | anchise | part. S=S | SpcNett. | | , | |
| | | | | Total Parts (S\$) | 63,950.00 | 21,480.00 |
| | | | | | - | |

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------------|--|-----------------|------------|----------|
| <u>Lab</u> | our Items | | | |
| 1 | LABOUR TO DISMANTLE & RENEW ALL ABOVE PARTS | New | 3,800.00 | 2,000.00 |
| 2 | LABOUR TO CHECK & CONNECT ALL LIGHTING & LAMP & WIRING | New | 380.00 | 0.00 |
| 3 | TO RUST PROOFING ON AFFECTED AREA | New | 850.00 | 0.00 |
| 4 | TO SPRAY & PAINTING ON AFFECTED AREA | New | 1,500.00 | 300.00 |
| | Gross Lal | bour Cost (S\$) | 6,530.00 | 2,300.00 |
| | Report was unsubmitted during thi | s print-out. | | |

< END OF ESTIMATES >