

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23000632/KPA3Q2**Date:** 24/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070066143
Claimant Vehicle No :	SJU5376D	Insured Vehicle No :	GBE9651L
Date of Loss:	16/01/2023	Nature of Claim:	TP
		Claim No:	9059754678SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU5376D	Engine No:	3ZRA422476
Make & Model:	TOYOTA WISH, 2.0 (A)	Chassis No:	JTDGJ20W605001586
Reg. Date:	15/12/2009 (Man. Year: 2009)	Odometer:	215519 km
Colour:	Metallic Grey		
Engine Capacity:	1987 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 9 mm	Rear Left Side:	Firenza 9 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	Firenza 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,198.35	1,638.49	559.86	25.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	440.00	740.00	62.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,378.35	2,078.49	1,299.86	38.48
Approved Total (Overridden) (S\$)		1,650.00		
Nett Amount (S\$)	3,378.35	1,650.00	1,728.35	51.16
+ Car Rental (3.0 x S\$120.00/day) (S\$)		360.00		
Nett Liability (S\$)		2,010.00		
Global Sum Settlement (S\$)		2,000.00		

INSPECTION

Date of Assignment:	17/01/2023		
Date Inspected:	17/01/2023	Inspected At:	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	870.23 FL	*584.70 FL
2	1		*FRONT BUMPER RH FOG LAMP COVER	Serviceable	66.93 FL	*- FL
3	1		*FRONT BUMPER RH FOG LAMP	Serviceable	329.12 FL	*- FL
4	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	66.60 FL	*66.60 FL
5	1		*FRONT BUMPER INNER FOAM	Cracked	100.47 FL	*100.47 FL
6	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
7	1		*FRONT BUMPER INNER REINFORCEMENT	Bent	329.78 FL	*329.78 FL
8	1		*SET FRONT FENDER UNDER SHIELD CLIPS	Necessary	30.00 FL	*30.00 FL
9	1		*RH HEADLAMP	Cracked	1,098.00 FL	*1,033.10 FL
					Sub Total (\$\$)	2,931.13 2,184.65
					- List Item Discount on L Items 25.00/25.00% (\$\$)	732.78 546.16
					Total Parts (\$\$)	2,198.35 1,638.49

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES FOR REMOVE /REFIT ,CUTTING /WELDING AND REPLACEMENT OF DAMAGES	New	500.00	200.00
2	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES	New	600.00	220.00
3	TO CHECK WIRINGS AND LIGHTINGS	New	40.00	20.00
4	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	40.00	0.00
Gross Labour Cost (S\$)			1,180.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >