

ASS. REC. BY:

REF:

M61

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STU 5376D Yr Regn: 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Wish

c.c

1987

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

215519

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDG J20W60 5001586

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FAMES

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

1/1/23

D.O.I.

17/1/2023

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

GIA not ready

Date/Time, File Pass to?



: Prel. Report



: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS, SI

F. P. M.

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

ump Sum / I.B.I: (\$

源 摩 哆 廠

GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not Withheld
L1 &
Money After Paint
2 day

REPAIR ESTIMATE SJU5376D

No.	Qty	List Items	
1	1	Front bumper	\$ <i>B</i> 870.23 ✓
2	1	Front bumper RH fog lamp cover	\$ <i>in</i> 66.93 X
3	1	Front bumper RH fog lamp	\$ <i>in</i> 329.12 X
4	1	Front bumper RH side retainer	\$ <i>dry</i> 66.60 ✓
5	1	Front bumper inner foam	\$ 100.47 7
6	1 set	Front bumper clips	\$ <i>in</i> 40.00 ✓
7	1	Front bumper inner reinforcement	\$ 329.78 7
8	1 set	Front fender under shield clips	\$ <i>in</i> 30.00 ✓
9	1	RH headlamp	\$ <i>cm</i> 1,098.00 ✓
			\$ 2,931.13
Less 25%			\$ 732.78
Total :			\$ 2,198.35

	Labour	
1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 500.00 200
2	To putty and spray Spray Paintings charges.	\$ 600.00 220
3	To check wirings and lightings.	\$ 40.00 20
4	To supply and apply anti rust treatment	\$ <i>in</i> 40.00 X
Total :		\$ 1,180.00

Total Parts and Labour : \$ 3,378.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: