

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS/AIS23000635/KQY3M4**Date:** 18/05/2023REFERENCE

Insured/Claimant:	FULCO LEASING PTE LTD	Policy No:	SP2004006721
Date of Loss:	14/01/2023	Nature of Claim:	OD
		Claim No:	202332004631

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK606X	Engine No:	1KDB015768
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5DR MT (M)	Chassis No:	JTFHT02P100249855
Reg. Date:	05/12/2019 (Man. Year: 2019)	Odometer:	68561 km
Colour:	Black		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$70,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Triangle 9 mm	Rear Left Side:	Triangle 9 mm
Front Right Side:	Triangle 9 mm	Rear Right Side:	Triangle 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,899.45	13,245.81	13,653.64	50.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	1,920.00	1,730.00	47.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,549.45	15,165.81	15,383.64	50.36
Approved Total (Overridden) (S\$)		11,900.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	29,049.45	10,400.00	18,649.45	64.20
+ GST 8.00/8.00% (S\$)	2,323.96	832.00	1,491.96	64.20
Nett Amount (S\$)	31,373.41	11,232.00	20,141.41	64.20

INSPECTION

Date of Assignment: 18/01/2023

Date Inspected: 19/01/2023 Inspected At:

FULCO AUTOCARE PTE LTD
176 SIN MING DRIVE
#03-02 SIN MING AUTOCARE
SINGAPORE 575721

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 May 2023)	
Parts:	N/A	TOYOTA HIACE 3.0 D TURBO 5DR MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK606X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	714.00 FL	*681.00 FL
2	1		*FRONT BUMPER SIDE RETAINER	O/S Distorted	299.20 FL	*114.30 FL
3	1		*FRONT BUMPER REINFORCEMENT	Bent	589.00 FL	*391.00 FL
4	1		*FRONT BUMPER LOWER GRILLE	Bent	258.00 FL	*109.48 FL
5	1		*FRONT GRILLE TOP	Cracked	354.00 FL	*354.00 FL
6	1		*FRONT GRILLE LOWER	Cracked	354.00 FL	*214.00 FL
7	2		*HEAD LAMP L+R	O/S Mtg Broken/N/S Mtg Cracked	3,360.00 FL	*2,976.00 FL
8	2		*HEAD LAMP LOWER BRACKET L+R	Serviceable	124.00 FL	*- FL
9	1		*TURBO COOLER AIR ARCH	Serviceable	245.00 FL	*- FL
10	1		*AIR CLEANER ASSY	Mtg Cracked	586.00 FL	*586.00 FL
11	2		*FRONT CORNER PANEL L+R	Serviceable	1,170.00 FL	*- FL
12	1		*BONNET EMBLEM	Necessary	158.00 FL	*78.00 FL
13	1		*BONNET	Bent	1,588.00 FL	*855.90 FL
14	1		*AIRCON COOLING COIL RESONATOR ASSY	Cracked	1,590.00 FL	*1,488.90 FL
15	1		*AIRCON BLOWER	Housing Cracked	1,340.00 FL	*1,340.00 FL
16	1		*FRONT AIR DUCT	Serviceable	248.00 FL	*- FL
17	1		*WIPER TANK	Serviceable	345.00 FL	*- FL
18	1		*WIPER TANK MOTOR	Serviceable	491.00 FL	*- FL
19	1		*RADIATOR ASSY	Punctured	2,082.00 FL	*1,856.90 FL
20	1		*CONDENSER ASSY	Punctured	1,955.00 FL	*1,410.50 FL
21	1		*WIPER LINKAGE	Serviceable	470.00 FL	*- FL
22	1		*WIPER MOTOR	Serviceable	780.00 FL	*- FL
23	1		*WINDSCREEN WIPER COWLING	Serviceable	988.00 FL	*- FL
24	1		*FRONT WINDSCREEN MOULDING	Not Necessary	433.00 FL	*- FL
25	1		*FRONT WINDSCREEN	Serviceable	2,200.00 FL	*- FL
26	2		*WIPER ARM	Serviceable	258.00 FL	*- FL
27	2		*WIPER BLADE	Serviceable	76.00 FL	*- FL
28	1		*DASHBOARD	Mtg Cracked	1,980.00 FL	*774.70 FL
29	1		*DASHBOARD TOP COMPARTMENT	Serviceable	339.00 FL	*- FL
30	1		*DASHBOARD LOWER GLOVE BOX	Serviceable	386.00 FL	*- FL
31	2		*FRONT BUMPER FOGLAMP COVER	Serviceable	750.00 FL	*- FL
32	1		*SUPPORT PANEL	Bent	773.00 FL	*578.00 FL
33	1		*BRAKE MASTER PUMP	Serviceable	832.00 FL	*- FL
34	1		*BRAKE BOOSTER	Serviceable	556.00 FL	*- FL
35	1		*BRAKE BOOSTER SWITCH	Serviceable	198.00 FL	*- FL
36	1		*BRAKE BRACKET	Repair	267.00 FL	*- FL
37	1		*AIR CLEANER SWITCH	Serviceable	167.00 FL	*- FL
38	1		*INTERCOOLER	Punctured	1,558.20 FL	*1,558.20 FL
39	1		*RADIATOR FAN ASSY	Cracked	2,078.90 FL	*1,281.10 FL
40	1		*COOLANT EXPANSION TANK	Dented	259.90 FL	*259.90 FL
41	2		*CHASSIS FRAME BRACKET UPPER	Bent	691.00 FL	*424.00 FL
42	2		*CHASSIS FRAME BRACKET LOWER	Bent	845.60 FL	*289.20 FL
43	1		*DASHBOARD INNER MEMBER	Repair	659.80 FL	*- FL
44	18		*FRONT BUMPER CLIPS	Not Necessary	99.00 FS	*- FS
45	6		*WINDSCREEN WIPER COWLING CLIPS	Not Necessary	33.00 FS	*- FS
46	1		*FRONT WINDSCREEN SEALANT	Not Necessary	140.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
47	1		*RADIATOR COOLANT	Necessary	80.00 FS	*30.00 FS	
					Sub Total (S\$)	35,748.60	17,651.08
					- List Item Discount on L Items 25.00/25.00% (S\$)	8,849.15	4,405.27
					Total Parts (S\$)	26,899.45	13,245.81

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTIONS. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,600.00	800.00
2	TO DISCONNECT AND REPLACE FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	100.00	20.00
3	TO REMOVE AND REPLACE A/C CONDENSER TO FACILITATE REPAIR WORK. TO CHARGE SYSTEM AND CHECK A/C FUNCTIONALITY	New	150.00	100.00
4	TO REMOVE AND REPLACE RADIATOR TO FACILITATE REPAIR. TO PERFORM PRESSURE TEST AND CHECK COOLING SYSTEM FUNCTIONALITY	New	150.00	50.00
5	REMOVE AND REPLACE DASHBOARD ASSY. CHECK STEERING COLUMN, BRAKE BOOSTER PUMP, FOOT PEDALS. REPAIR, CHECK, REPLACE NECESSARY DAMAGED PARTS	New	400.00	250.00
6	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA / PANEL	New	1,000.00	700.00
7	TO REMOVE AND REPLACE FRONT WINDSCREEN	New	150.00	0.00
8	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
Gross Labour Cost (S\$)			3,650.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >