

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI23000636/RVY3E2**Date:** 20/01/2023**REFERENCE**

Insured/Claimant: CA TRANSPORTATION & WAREHOUSING PTE LTD Policy No: DMCG22005300

Date of Loss: 13/01/2023

Nature of Claim: OD

Claim No: CDMCG23000095

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE2928A	Engine No:	GH11742602
Make & Model:	UD TRUCKS GKB85ELDHNT, 10.8 D (M)	Chassis No:	JNCM1F1AXHU019629
Reg. Date:	08/05/2017 (Man. Year: 2017)	Odometer:	312092 km
Colour:	White		
Engine Capacity:	10837 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8/8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,188.90	9,746.55	4,442.35	31.31
Miscellaneous Items	220.00	220.00	0.00	0.00
Labour	2,840.00	1,840.00	1,000.00	35.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,248.90	11,806.55	5,442.35	31.55
- Excess (S\$)	0.00	1,500.00	-1,500.00	
(S\$)	17,248.90	10,306.55	6,942.35	40.25
+ GST 8.00/8.00% (S\$)	1,379.91	824.52	555.39	40.25
Nett Amount (S\$)	18,628.81	11,131.07	7,497.74	40.25

INSPECTION

Date of Assignment:	19/01/2023	Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	19/01/2023	Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(FOR MANDATE ONLY)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Jan 2023)	
Parts:	N/A	UD TRUCKS GKB85ELDHNT 10.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE2928A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GRILLE ASSY TOP (WCP)	Repair	485.00 F	*- F
2	1		*GRILLE ASSY LOWER (WCP)	Cracked	450.00 F	*450.00 F
3	1		*FRONT BUMPER STEP CENTER (WCP)	Cut	25.00 F	*25.00 F
4	1		*FRONT BUMPER STEP LH (WCP)	Cracked	51.00 F	*51.00 F
5	1		*CORNER PANEL LOWER COVER LH (WCP)	* Check	20.00 F	*- F
6	1		*FRONT BUMPER BASE (WCP)	Bent	950.00 F	*950.00 F
7	1		*FRONT BUMPER CENTER (WCP)	Bent	500.00 F	*500.00 F
8	1		*FRONT BUMPER CORNER (WCP)	Bent	450.00 F	*450.00 F
9	1		*FRONT BUMPER CORNER, END PIECES (WCP)	Cracked	65.00 F	*65.00 F
10	1		*FRONT BUMPER GRILLE, CTR (WCP)	Missing	137.50 F	*137.50 F
11	1		*FRONT BUMPER GRILLE LH (WCP)	Missing	65.00 F	*65.00 F
12	1		*SIDE STEP (WCP)	Cracked	120.00 F	*120.00 F
13	1		*SIDE STEP REFLECTOR (WCP)	Missing	15.00 F	*15.00 F
14	1		*SIDE STEP BACK COVER (WCP)	Cracked	85.00 F	*85.00 F
15	1		*SIDE STEP BRKT (2PCS)(WCP)	Bent (1Pc Only)	560.00 F	*280.00 F
16	1		*HEADLAMP (WCP)	* Check	600.00 F	*- F
17	1		*FRONT LAMP (WCP)	Dented	85.00 F	*85.00 F
18	1		*FOG LAMP (WCP)	Scratched	90.00 F	*90.00 F
19	1		*UNDERNEATH COVER, FRONT (WCP)	Cracked	258.00 F	*258.00 F
20	1		*FAN SHROUD (WCP)	* Check	300.00 F	*- F
21	1		*AIR COOLER (WCP)	Bent	2,089.00 F	*2,089.00 F
22	1		*COOLANT HOSE, TOP (WCP)	* Check	95.00 F	*- F
23	1		*RADIATOR (WCP)	Bent	1,400.00 F	*1,400.00 F
24	1		*NET RADIATOR (WCP)	Repair	850.00 F	*- F
25	1		*FAN ASSY (WCP)	Cut	1,700.00 F	*1,700.00 F

Report was unsubmitted during this print-out.

1/20/23, 2:14 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*RADIATOR SUPPORT BRKT (WCP)	Bent	45.00 F	*45.00 F
27	1		*FAN SHROUD SUPPORT (WCP)	* Check	350.00 F	*- F
28	1		*FAN SHROUD, INNER (WCP)	* Check	1,058.50 F	*- F
F=Franchise part.						
Sub Total (S\$)					12,899.00	8,860.50
+ Margin on L,N Items 10.00/10.00% (S\$)					1,289.90	886.05
Total Parts (S\$)					14,188.90	9,746.55
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	3	COOLANT (NECESSARY)	180.00	180.00
2	1	FRONT NUMBER PLATE (BENT)	40.00	40.00
Sub Total (\$)			220.00	220.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK FRONT BUMPER BRACKET & REPLACE ACCIDENT DAMAGED PARTS RELATED TO ACCIDENT	New	600.00	500.00
2	TO SPRAY PAINT ON FRONT GRILLE, BUMPER CENTER, BUMPER CORNER, SIDE STEP BACK COVER	New	1,700.00	1,000.00
3	TO CRANE OUT THE RADIATOR ASSY, TURBO INTERCOOLER	New	500.00	300.00
4	TO ADJUST FOCUS HEADLAMP AND CHECK ALL LIGHTING FUNCTIONING	New	40.00	40.00
Gross Labour Cost (\$)			2,840.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

Pre Review done base on survey information provided
Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.

Review By : Insurlogic
Part by Part : \$11,806.55
Check items : \$2665.85
Total : \$14,472.40
Repair duration : 5 days