



Case Details

Case Reference Number : TAX/01/23/2040
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5384D

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-20329-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : income insurance limited
 Accident Date and Time : 17/01/2023 11:25 PM
 Vehicle Age(In Months) :-

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	SMRT Recommendation					Surveyor Approval				Remarks
					Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			BUMPER REAR	1	478.90	478.90	25.00	359.17	Replace	1	359.17	Replace	de
Standard	Main			BUMPER CLIPS (10 PCS)	10	2.40	24.00	25.00	18.00	Replace	10	18.00	Replace	un
Standard	Main			BUMPER REINFORCEMENT REAR	1	234.70	234.70	25.00	176.02	Replace	1	176.02	Replace	bt
Standard	Main			ARM SUB-ASSY. RR BUMPER RH	1	157.90	157.90	25.00	118.43	Replace	0	0	Not Give	Xun
Standard	Main			ARM SUB-ASSY. RR BUMPER LH	1	157.90	157.90	25.00	118.43	Replace	0	0	Check	Xun
Standard	Main			ANTENNA,ELECTRICAL LOWER REAR	1	208.10	208.10	10.00	187.29	Replace	0	0	Not Give	Xun
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check	Xun
Standard	Main			BUMPER SIDE RETAINER RR/LH	1	108.70	108.70	25.00	81.53	Replace	1	81.53	Replace	de
Standard	Main			BUMPER SEAL, RR LH	1	101.80	101.80	25.00	76.35	Replace	0	0	Not Give	Xun
Standard	Main			BUMPER LIP COVER RR/LH	1	93.90	93.90	25.00	70.43	Replace	0	0	Not Give	Xun
Standard	Main			BUMPER LIP REAR	1	301.90	301.90	25.00	226.42	Replace	0	0	Not Give	Xun
Standard	Main			END PANEL	1	755.10	755.10	25.00	566.33	Replace	0	0	Check	Xun
Standard	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	Xun
Standard	Main			FENDER RR/LH	1	980.80	980.80	25.00	735.60	Replace	0	0	Not Give	Xun
Standard	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	Xun
Standard	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	Xun
Total Spare Part Cost									3,658.94				Surveyor Total	1,191.46
Lump Sum Discount (%)									20.00				Lump Sum Dis (%)	20
Final Spare Part Cost									2,920.91				Final Sur Total	953.17

1/18/23, 3:14 PM

SMRT Recommendation														Surveyor Approval		Remarks	ELL
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace				
Standard	Main			TAIL LAMP BRACKET, LH	1	35.20	35.20	25.00	26.40	Replace	0	0	Check	✓ Xun			
Standard	Main			TAIL LAMP LH	1	618.60	618.60	10.00	556.74	Replace	1	556.74	Replace	✓ cut			
Standard	Main			LID ASSY, FUEL	1	116.80	116.80	25.00	87.60	Replace	0	0	Not Give	✓ Xun			
Standard	Main			STICKER PETROL ONLY	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	✓ Xun			
Total Spare Part Cost									3,658.94	Surveyor Total		1,191.46					
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)							
Final Spare Part Cost									2,920.91	Final Sur Total		953.17					

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION LH	676.00	200	
Total:			676.00	200.00	✓

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FUEL LID COVER	180.00	Xun	
2	Main	TO RESPRAY REAR BUMPER	378.00	200	
3	Main	TO RESPRAY REAR PANEL	180.00	0 Xun	
4	Main	TO RESPRAY BUMPER BEAM	180.00	0 Xun	
5	Main	TO RESPRAY REAR FENDER LH	378.00	0 Xun	
Total:			1,296.00	200.00	✓

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 Xun	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	30	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0 Xun	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	
Total:			500.00	60.00	✓

SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
100.00	0	
500.00	60.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,920.91	953.17
Total Labour Cost	676.00	200.00
Total Spray Painting	1,296.00	200.00
Other	500.00	60.00
Overall Total	5,392.91	1,413.17
Lump Sum Repair Option	☐	☒
Lump Sum Total	5,400.00	1,400.00
Surveyor Approved Amount		1,400.00
No of Repair Days*	5	2
Remarks		LUMPSUM REPAIR / AFTER REPAIR PHOTOS, FOR CHECK ITEM and REPLACE ITEM. PLEASE CALL SURVEYOR TAUFIKH HP 9749 5749 / EMAIL: taufikh@lkkauto.com
Surveyor Name		Taufikh
Signature		

Save Clear

Survey Date 18/01/2023

634.73
 556.74
 200
 200
 60
 1651.47
 20% - 1321.17
 4/5 \$1300
 2 days
 #

Taufikh 97495749
 wop 18/1/23 23pm
 2 days
 LK Resey after repair
 Taufikh @ lkkauto.com

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: