

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/MSG23000641/UQY3M4**Date:** 10/02/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001915886
<b>Claimant Vehicle No :</b>	SNC6175H	<b>Insured Vehicle No :</b>	SMJ1669H
Date of Loss:	19/01/2023	Nature of Claim:	TP
		Claim No:	300433

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNC6175H</b>		
Make & Model:	NISSAN SERENA, 1.2 L HIGHWAY STAR PREMIUM E-POWER (A)	Engine No:	HR12248289K
Reg. Date:	30/10/2021 (Man. Year: 2021)	Chassis No:	JN1EBAC27Z0001163
Colour:	Brown	Odometer:	29228 km
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	20,673.70	5,467.77	15,205.93	73.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	2,210.00	1,330.00	37.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>24,213.70</b>	<b>7,677.77</b>	<b>16,535.93</b>	<b>68.29</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>1,937.10</b>	<b>614.22</b>	<b>1,322.88</b>	<b>68.29</b>
<b>Nett Amount (S\$)</b>	<b>26,150.80</b>	<b>8,291.99</b>	<b>17,858.81</b>	<b>68.29</b>

INSPECTION

Date of Assignment:	01/02/2023		
Date Inspected:	19/01/2023	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	6.0 days		

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 01 Feb 2023)**Parts:** M1-MPV NISSAN SERENA 1.2 L HIGHWAY STAR PREMIUM E-POWER (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SNC6175H)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,685.00 F	*1,527.10 FN
2	1		*REAR BUMPER PDC SENSORS @\$255.00 2PIECES	Shorted (1Piece Only)	510.00 F	*245.00 FN
3	4		*REAR BUMPER PDC SENSOR HOLDERS @\$25.00	Necessary	100.00 F	*100.00 FN
4	1		*REAR BUMPER SIDE GRILLES @\$265.00 2PIECES	N/s Cut (1Piece Only)	530.00 F	*162.00 FN
5	2		*REAR BUMPER SIDE RETAINERS @\$85.00	Not Necessary	170.00 F	*- FN
6	1		*SET REAR BUMPER CLIPS	Necessary	45.00 F	*45.00 FN
7	1		*REAR AIR VENT O/S	Not Necessary	182.00 F	*- FN
8	1		*TAILGATE GLASS ASSY	Not Necessary	6,875.00 F	*- FN
9	1		*TAILGATE	Badly Dented	4,742.00 F	*1,880.40 FN
10	1		*TAILGATE E-POWER EMBLEM	Necessary	105.00 F	*101.90 FN
11	1		*TAILGATE REAR LOGO	Not Necessary	48.00 F	*- FN
12	1		*TAILGATE HIGHWAY EMBLEM	Necessary	90.00 F	*54.90 FN
13	1		*TAILGATE STAR EMBLEM	Necessary	88.00 F	*52.00 FN
14	1		*TAILGATE WEATHERSTRIP	Twisted	299.00 F	*245.00 FN
15	1		*TAILGATE INNER LOCK	Twisted/Damaged	509.00 F	*215.60 FN
16	1		*TAILGATE INNER TRIM BOARD	Cracked	615.00 F	*321.60 FN
17	1		*TAILLAMP N/S	Not Necessary	660.30 F	*- FN
18	1		*TAILLAMP LOWER GARNISH N/S	Deformed	484.90 F	*388.60 FN
19	1		*TAILLAMP LOWER GARNISH SIDE RETAINER N/S	Not Necessary	146.00 F	*- FN
20	1		*REAR END PANEL OUTER	Dented	855.00 F	*322.60 FN
21	1		*REAR END PANEL INNER	Dented	455.10 F	*305.00 FN
22	1		*REAR END PANEL TOP GARNISH	Twisted	242.00 F	*108.60 FN
23	1		*REAR FENDER INNER TRIM BOARD N/S	Not Necessary	628.20 F	*- FN
24	1		*REAR FENDER UNDER TRIM N/S	Not Necessary	366.20 F	*- FN
25	1		*SET REAR FENDER UNDER TRIM CLIPS N/S	Not Necessary	30.00 F	*- FN
26	1		*REAR WINDSCREEN MOULDING	Not Necessary	168.00 F	*- FN
27	1		*REAR WINDSCREEN SEALANT	Not Necessary	45.00 F	*- FN

F=Franchise part. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>20,673.70</b>	<b>6,075.30</b>
<b>- Nett Item Discount on N Items 0.00/10.00% (\$\$)</b>	0.00	607.53
<b>Total Parts (\$\$)</b>	<b>20,673.70</b>	<b>5,467.77</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX TAILGATE MECHANISM	New	100.00	80.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	180.00	80.00
6	TO RESET & REPROGRAMME SYSTEM	New	180.00	0.00
7	TO SPRAY RUST PROOFING	New	100.00	60.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	800.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,000.00
			<b>Gross Labour Cost (S\$)</b>	<b>3,540.00</b>
				<b>2,210.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >