

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
 To Inspect Vehicle No: SNC 6175H  
 at Workshop m/s Re.  
 of \_\_\_\_\_  
 Insured: SMJ 1669H  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record) \_\_\_\_\_  
 Make of Veh: \_\_\_\_\_

Veh No: SNC 6175H Yr Regn: 30/10/21  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CA/  
 Make: Nissan Serena c.c. 1198  
 Colour: Brown A/C: Insured / Std / NI / NA  
 Sp. Reading: 29228 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JNIEBAC2720001163  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195/60R16  
 R: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 6165  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 6 days Res.: Yes or No  
 Lum Sum: 1.31 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS 2700  
 Date: \_\_\_\_\_ Person Contacted: LTA 876730  
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front 2 mm Rear 2 mm  
 R/Bal. 2 mm R/Bal. 2 mm  
 L/Bal. 8 mm L/Bal. 8 mm  
 D.O.A. 19/01/23 D.O.I. 19/01/23  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
20/1/23  
in wksp SMJ/405E Amplution parts  
P/2 7677-77 Used 7702.83, 50%

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: 6  
 Resurvey No. of Trip: 4

1) Date/Time, File Return to?  
 2) \_\_\_\_\_

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech. Invs (\$ )  
 : Weekend (\$ )

Survey Fee:	
Transportation:	
_____S + RS, ___SI	
Photos	
Others	
TOTAL	

Report Format: NER TP  
 Lump Sum / I.B.I.: (\$ 7677.77 )

submit to ins

not allowed

19/01/23

P/P# 7677-77

6 days

FASTECH AUTO PTE LTD  
1 Kaki Bukit Ave 6 #01-48 Autobay  
Singapore 417883  
Tel No: 67452063/ 67467158 Fax No: 67458520  
Tax Reg No : 200006262D P/P# 7677-77

**LKK Auto Consultants** hence notify  
**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

NETT ITEM

1PC	REAR BUMPER	Dis	1527.10	\$1,685.00	✓
2PCS	REAR BUMPER PDC SENSORS @\$255.00	skuld	245	\$510.00	1pc
4PCS	REAR BUMPER PDC SENSOR HOLDERS @\$25.00	all		\$100.00	✓
2PCS	REAR BUMPER SIDE GRILLES @\$265.00	ntscun	162	\$530.00	1pc
2PCS	REAR BUMPER SIDE RETAINERS @\$85.00	11		\$170.00	X
1SET	REAR BUMPER CLIPS	all		\$45.00	✓
1PC	REAR AIR VENT O/S	11		\$182.00	X
1PC	TAILGATE GLASS ASSY	11		\$6,875.00	X
1PC	TAILGATE	bedgion	1880.40	\$4,742.00	✓
1PC	TAILGATE 'E-POWER' EMBLEM	all	101.90	\$105.00	✓
1PC	TAILGATE REAR LOGO	11		\$48.00	X
1PC	TAILGATE 'HIGHWAY' EMBLEM	all	54.90	\$90.00	✓
1PC	TAILGATE 'STAR' EMBLEM	all	52.00	\$88.00	✓
1PC	TAILGATE WEATHERSTRIP	twi	245.00	\$299.00	✓
1PC	TAILGATE INNER LOCK	twi/Boyl	215.60	\$509.00	✓
1PC	TAILGATE INNER TRIM BOARD	one	321.60	\$615.00	✓
1PC	TAILLAMP N/S	11		\$660.30	X
1PC	TAILLAMP LOWER GARNISH N/S	2e	388.60	\$484.90	✓
1PC	TAILLAMP LOWER GARNISH SIDE RETAINER N/S	11		\$146.00	X
1PC	REAR END PANEL OUTER	DD	322.60	\$855.00	✓
1PC	REAR END PANEL INNER	DD	325.00	\$455.10	✓
1PC	REAR END PANEL TOP GARNISH	twi	108.60	\$242.00	✓
1PC	REAR FENDER INNER TRIM BOARD N/S	11		\$628.20	X
1PC	REAR FENDER UNDER TRIM N/S	11		\$366.20	X
1SET	REAR FENDER UNDER TRIM CLIPS N/S	11		\$30.00	X
1PC	REAR WINDSCREEN MOULDING	11		\$168.00	X
1PC	REAR WINDSCREEN SEALANT	11		\$45.00	X
			(102)	\$11,860.60	

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REAR PDC SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO DISMANTLE & REFIX TAILGATE MECHANISM	\$100.00	80
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$180.00	80
TO RESET & REPROGRAMME SYSTEM	11 \$180.00	X
TO SPRAY RUST PROOFING	\$100.00	60
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,200.00	800
TO PUTTY & SPRAY PAINTING	\$1,500.00	1000
<b>TOTAL</b>	<b>\$15,400.60</b>	

P-6075-3  
107  
5-467-77

2210