3/24/23, 10:47 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI23000645/UVP3Q2

24/03/2023 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMPCSNW00065502200

Odometer:

Claimant Vehicle No:

FBH9K

Insured Vehicle No:

SLJ5112H

Date of Loss:

20/12/2022

Nature of Claim: TP

Claim No:

3849 km

SNM22D209181/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

FBH9K Reg No:

A74B12M03226282 Make & Model: BMW R1200 GSA, 1.2 Engine No: Reg. Date: 28/04/2022 (Man. Year: 2022) Chassis No: WB10M1103N6F42366

Colour: White

Engine Capacity: Market Value/New Car 1254 cc

Price:

N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/70 R19 170/60 R17 Rear Tyre Size: Front Left Side: Rear Left Side: Michelin 6 mm Michelin 6 mm

Front Right Side: Rear Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,847.00	1,944.00	3,903.00	66.75
Miscellaneous Items		0.00	0.00	0.00	
Labour		470.00	380.00	90.00	19.15
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
N	lett Amount (S\$)	6,317.00	2,324.00	3,993.00	63.21

INSPECTION

Date Inspected:

Date of Assignment: 26/01/2023

> Sanfu Motor Pte Ltd (Kaki Bukit) 19/01/2023 Inspected At:

1 Kaki Bukit Ave 6, #02-43 Autobay @ Kaki Bukit

Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA VERON CHEN Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 24 Mar 2023)

Parts: N/A BMW R1200 GSA 1.2 (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBH9K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SUPPORT BAR (PANNIER BRACKET)	Bent	351.00 F	*351.00 FL
2	1		*REAR FENDER (HUGGER)	Missing	486.00 F	*286.00 FL
3	1		*ENGINE PROTECTOR (L&R) (SET)	O/S Cut	2,465.00 F	*1,100.00 FL
4	1		*RH CYLINDER HEAD COVER	Cut	1,519.00 F	*423.00 FL
5	1		*RH RIDER FOOTREST	Serviceable	486.00 F	*- FL
6	1		*STEERING CONE & BEARING	Not Necessary	120.00 FS	*-FS
7	1		*FRONT FORK ALIGNMENT	Not Necessary	220.00 FS	*- FS
8	1		*FRAME ALIGNMENT	Not Necessary	200.00 FS	*-FS
F=Fra	nchise	part. S=SpcN	lett. L=ListItemDisc.	-		
				Sub Total (S\$)	5,847.00	2,160.00
			- List Item Discount on L Iter	ns 0.00/10.00% (S\$)	0.00	216.00
				Total Parts (S\$)	5,847.00	1,944.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
<u>Lab</u>	our Items						
1	WHEEL ALIGNMENT	New	120.00	80.00			
2	WORKMANSHIP TO RENEW DAMAGE PARTS & AREAS	New	350.00	300.00			
		Gross Labour Cost (S\$)	470.00	380.00			
Report was unsubmitted during this print-out.							

< END OF ESTIMATES >