

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS23000646/KVY3M4**Date:** 24/03/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SPMF1000000519
Claimant Vehicle No :	SNC5640M	Insured Vehicle No :	SNA4113K
Date of Loss:	14/01/2023	Nature of Claim:	TP
		Claim No:	SNA4113K

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNC5640M		
Make & Model:	SKODA OCTAVIA, 1.5 AMBITION 1.5 TSI MHEV (A)	Engine No:	DFY076758
Reg. Date:	28/10/2021 (Man. Year: 2021)	Chassis No:	TMBBR7NX9MY178543
Colour:	Red	Odometer:	11911 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,231.50	2,152.33	2,079.17	49.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	875.00	835.00	48.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,941.50	3,027.33	2,914.17	49.05
Approved Total (Overridden) (\$\$)		2,400.00		
Nett Amount (\$\$)	5,941.50	2,400.00	3,541.50	59.61
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	18/01/2023		
Date Inspected:	30/01/2023	Inspected At:	TRUST AUTOWORKS 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569537
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Mar 2023)
Parts:	143	SKODA OCTAVIA 1.5 AMBITION 1.5 TSI MHEV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC5640M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	950.00 FL	*- FL
2	1		*REAR BOOT LID EMBLEM SKODA	Necessary	55.00 FL	*55.00 FL
3	1		*REAR BOOT LID EMBLEM OCTAVIA	Necessary	75.00 FL	*75.00 FL
4	1		*REAR BOOT LID BATCH	Necessary	25.00 FL	*25.00 FL
5	1		*REAR BUMPER	Buckled/Cracked	1,050.00 FL	*1,050.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Repair	480.00 FL	*- FL
7	1		*REAR BUMPER INNER TOP BEAM	Cracked	185.00 FL	*185.00 FL
8	1		*REAR N/S BUMPER SIDE RETAINER	Serviceable	115.00 FL	*- FL
9	1		*REAR N/S BUMPER REFLECTOR	Cracked	195.00 FL	*59.81 FL
10	1		*REAR BUMPER LOWER GARNISH	No such part	355.00 FL	*- FL
11	1		*REAR BUMPER REVERSE SENSOR	Shorted (1Piece Only)	550.00 FL	*275.00 FL
			2PIECES			
12	1		*REAR BUMPER LOWER SKIRT	Cracked	600.00 FS	*600.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					4,635.00	2,324.81
- List Item Discount on L Items 10.00/10.00% (S\$)					403.50	172.48
Total Parts (S\$)					4,231.50	2,152.33
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING, WELDING ETC	New	700.00	400.00
2	TO PUTTY AND SPRAY PAINT	New	700.00	400.00
3	CHECK & RECONNECT WIRING	New	30.00	15.00
4	TO RESPRAY ANTI-RUST PROOFING TREATMENT	New	100.00	0.00
5	REMOVE/RENEW REAR BUMPER SENSOR AND TO RESET TO FACTORY SPECIFICATION	New	180.00	60.00
Gross Labour Cost (\$\$)			1,710.00	875.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >