



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 2592D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	900.00	538.00
1	HEADLAMP - RIGHT	CUT	1,200.00	1,200.00
	LESS 20% DISCOUNT		-420.00	-347.60
			1,680.00	1,390.40
	<u>SPECIAL NETT ITEMS</u>			
1	CLIPS , RIVETS & SCREWS (SN)	NECESSARY	100.00	30.00
			100.00	30.00
	<u>LABOUR</u>			
	TO PUTTY & SPRAY PAINT OF AFFECTED AREA.		1,000.00	200.00
	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.		1,000.00	250.00
	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE.		150.00	30.00
	TO REMOVE & REINSTALL SENSORS.	NOT NECESSARY	100.00	-
			2,250.00	480.00
GRAND TOTAL			4,030.00	1,900.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/FCI23000649/Any3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.