



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23000649/Any3m4 Date: 20/04/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBG 1601Z	Veh. Inspected	SLN 2592D
Policy No.		Coverage (\$)	0.00
Claim No.	D23000264MCVP	Excess (\$)	0.00
Assign From	HARMINDER KAUR	Assign Date	19/01/2023
2. Vehicle Particulars & Condition			
Make & Model	HONDA FIT	c.c	1317
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GK31216501	Colour	BRONZE
Odometer	179026 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/55R15	MICHELIN	6 mm
L/H Front Tyre	195/55R15	MICHELIN	6 mm
R/H Rear Tyre	195/55R15	MICHELIN	6 mm
L/H Rear Tyre	195/55R15	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/01/2023	Inspection Date	08/02/2023
Survey held at	JACK CARS ENTERPRISE PTE LTD BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408700		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	