



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 4298G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR O/S TAIL-GATE ASSY	TO REPAIR SEE LABOUR	1,850.00	-
1	REAR O/S TAIL-GATE GLASS	SHATTERED	950.00	485.00
1	REAR O/S TAIL-GATE EMBLEM "LOGO"	NECESSARY	85.00	85.00
1	REAR O/S TAIL-GATE EMBLEM "PROFESSIONAL"	NECESSARY	95.00	95.00
1	REAR O/S TAIL-GATE OUTER GARNISH	SERVICEABLE	285.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	950.00	-
2	REAR REVERSE SENSOR @\$280.00	SERVICEABLE	560.00	-
	LESS 10% DISCOUNT		-477.50	-66.50
			4,297.50	598.50
<u>NETT ITEMS</u>				
1	REAR STICKER " 6 PAX " (N)	NECESSARY	15.00	15.00
1	REAR TAIL-GATE GLASS SEALANT (N)	NOT NECESSARY	35.00	-
			50.00	15.00
<u>LABOUR</u>				
	REMOVE/RENEW ABOVE DAMAGED PARTS INCLUDING KNOCKING ETC. INCLUSIVE OF THE REPAIR OF REAR O/S TAIL-GATE ASSY AND REAR BUMPER.		500.00	200.00
	TO PUTTY AND SPRAY PAINT.		600.00	400.00
	REMOVE/REFIT BOTH REAR TAIL-GATE GLASS.		80.00	50.00
			1,180.00	650.00
GRAND TOTAL			5,527.50	1,263.50
RECOMMENDED COST OF REPAIRS				1,263.50

Report Ref No. CS/FCI23000650/Kvy3m4

MARKET VALUE: \$27,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$11,997.00=NETT VALUE: \$15,003.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.