

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS23000653/TVY3E2**Date:** 21/03/2023**REFERENCE**

Insured/Claimant: UBTS PTE LTD Policy No: AIS/2023/0000375/001677
Date of Loss: 11/01/2023 Nature of Claim: OD Claim No: 202332004875

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE3860D**
Make & Model: SCANIA P440CB, 12.7 D 8x4 EHZ (M) Engine No: DC13112L017033663
Reg. Date: 22/12/2017 (Man. Year: 2017) Chassis No: YS2P4X20005480009
Colour: White Odometer: 528157 km
Engine Capacity: 12742 cc
Market Value/New Car Price: S\$84,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 315/80 R22.5 Rear Tyre Size: 315/80 R22.5 (D)
Front Left Side: Double Coin 8 mm Rear Left Side: Double Coin 8/8 mm
Front Right Side: Double Coin 8 mm Rear Right Side: Double Coin 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	85,960.79	67,151.45	18,809.34	21.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,900.00	4,825.00	2,075.00	30.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	92,860.79	71,976.45	20,884.34	22.49
Approved Total (Overridden) (S\$)		50,000.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	91,360.79	48,500.00	42,860.79	46.91
+ GST 8.00/8.00% (S\$)	7,308.86	3,880.00	3,428.86	46.91
Nett Amount (S\$)	98,669.65	52,380.00	46,289.65	46.91

INSPECTION

Date of Assignment: 19/01/2023
Date Inspected: 27/01/2023 Inspected At: ASM Automotive Services Pte Ltd (HQ)
Estimated Period of Repair: 14.0 days No.13 Pioneer Sector 1
Singapore 628424

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Mar 2023)	
Parts:	N/A	SCANIA P440CB 12.7 D 8x4 EHZ (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE3860D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT VIEW MIRROR (WCP)	Cracked	275.04 F	*275.04 F
2	1		*FRONT WINDSCREEN (WCP)	Cracked	1,080.00 F	*1,080.00 F
3	1		*WIPER ARM, LH (WCP)	Bent	382.20 F	*382.20 F
4	1		*WIPER BLADE, LH (WCP)	Cut	70.56 F	*70.56 F
5	1		*MEMBER PANEL, LH (WCP)	Cracked	154.08 F	*154.08 F
6	1		*MEMBER PANEL, CENTER (WCP)	Bent	131.64 F	*131.64 F
7	1		*MEMBER PANEL, RH (WCP)	Deformed	154.20 F	*154.20 F
8	1		*SPACE FRAME (WCP)	Bent	2,431.80 F	*2,431.80 F
9	2		*SPACE FRAME HINGE, LH & RH (WCP)	Not Necessary	783.12 F	*- F
10	1		*FRONT UPPER PANEL (WCP)	Bent	1,696.92 F	*1,696.92 F
11	1		*LOGOTYPE SCAN (WCP)	Necessary	89.64 F	*89.64 F
12	1		*LOGOTYPE IA (WCP)	Necessary	74.16 F	*74.16 F
13	1		*FRONT UPPER PANEL RAIL (WCP)	Bent	868.68 F	*868.68 F
14	1		*FRONT UPPER PANEL TOP MESH, LH (WCP)	Bent	133.68 F	*133.68 F
15	1		*FRONT UPPER PANEL CENTER MESH, TOP (WCP)	Bent	272.64 F	*272.64 F
16	1		*FRONT UPPER PANEL CENTER MESH, BOTTOM (WCP)	Bent	285.96 F	*285.96 F
17	15		*MESH CLAMP (WCP)	Necessary	61.20 F	*61.20 F
18	2		*CAB CORNER - OUTER, LH & RH (WCP)	Cracked	1,958.88 F	*1,958.88 F
19	2		*CAB CORNER - INNER, LH & RH (WCP)	Deformed	202.80 F	*202.80 F
20	1		*WIPER LINK (WCP)	Not Necessary	722.88 F	*- F
21	1		*WIPER LINK BRACKET (WCP)	Bent	1,590.00 F	*1,590.00 F
22	1		*WIPER MOTOR (WCP)	Not Necessary	831.12 F	*- F
23	1		*EXPANSION TANK (WCP)	Not Necessary	922.08 F	*- F
24	1		*EXPANSION TANK SQUARE CASING (WCP)	Deformed	90.36 F	*90.36 F
25	1		*AIR DUCT ASSY	Cracked	793.68 F	*793.68 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		(WCP) *FAN MOTOR ASSY	Cracked	1,551.12 F	*1,551.12 F
27	1		(WCP) *HEAT EXCHANGE CORE	Not Necessary	932.04 F	*- F
28	1		(WCP) *EVAPORATOR COIL	Not Necessary	1,274.52 F	*- F
29	1		(WCP) *HVAC ASSY	Not Necessary	711.36 F	*- F
30	1		(WCP) *AIRCON RECEIVER DRIER	Distorted	218.40 F	*218.40 F
31	1		(WCP) *AIRCON CONDENSER	Bent	2,204.64 F	*2,204.64 F
32	1		(WCP) *CHARGE AIR COOLER	Bent	3,510.12 F	*3,510.12 F
33	1		(WCP) *RADIATOR	Bent	2,933.16 F	*2,933.16 F
34	2		(WCP) *RADIATOR FASTENER/MOUNTING, LH & RH	Bent	585.12 F	*585.12 F
35	1		(WCP) *FRONT CABIN BRACKET, LH & RH	O/S Bent / N/S Not Necessary	3,622.80 F	*1,811.40 F
36	2		(WCP) *FRONT CABIN AIR SPRING (SHOCK ABSORBER), LH & RH	Bent	1,406.64 F	*1,406.64 F
37	2		(WCP) *AIR SPRING LINK YOKE, LH & RH	Bent	515.76 F	*515.76 F
38	1		(WCP) *TURRET, LH & RH	O/S Broken / N/S Not Necessary	1,890.48 F	*945.24 F
39	1		(WCP) *TURRET CAP, LH & RH	O/S Broken / N/S Not Necessary	673.68 F	*336.84 F
40	1		(WCP) *ANTI-ROLL BAR ASSY WITH BUSHING & WASHER	Bent	3,954.72 F	*3,954.72 F
41	1		(WCP) *AIR PIPING (LEFT)	Dented	143.00 F	*143.00 F
42	2		(WCP) *CABIN LOCK, LH & RH	Bent	764.16 F	*764.16 F
43	1		(WCP) *CABIN LOCK WIRE ROPE	Not Necessary	367.20 F	*- F
44	1		(WCP) *AIR INTAKE, CENTER	Deformed	657.00 F	*657.00 F
45	1		(WCP) *AIR CLEANER ASSY	Cracked	3,334.32 F	*3,334.32 F
46	2		(WCP) *HEADLAMP SEAL, LH & RH	Deformed	463.20 F	*463.20 F
47	1		(WCP) *HEADLAMP INNER BRACKET, RH	Bent	999.60 F	*999.60 F
48	1		(WCP) *HEADLAMP SIDE BRACKET, RH	Not Necessary	228.96 F	*- F
49	1		(WCP) *HEADLAMP INNER HOUSING, RH	Distorted	544.32 F	*544.32 F
50	1		(WCP) *HEADLAMP ASSY, RH	Cracked	478.44 F	*478.44 F
51	1		(WCP) *FRONT SIGNAL LAMP, RH	Cracked	138.00 F	*138.00 F
52	1		(WCP) *HEADLAMP COVER STRIP, RH	Deformed	34.32 F	*34.32 F
53	1		(WCP) *HEADLAMP PROTECTION MESH, RH	Missing	272.88 F	*272.88 F
54	1		(WCP) *PROTECTION MESH BRACKET (INNER), RH	Bent	129.12 F	*129.12 F
55	1		(WCP) *PROTECTION MESH BUSH, RH	Missing	336.84 F	*336.84 F
56	1		(WCP) *PROTECTION MESH BRACKET (OUTER), RH	Distorted	129.12 F	*129.12 F
57	1		(WCP) *FRONT LOWER PANEL, RH	Bent	165.48 F	*165.48 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
58	1		*FRONT LOWER PANEL BRACKET, RH (WCP)	Bent	3,194.52 F	*3,194.52 F
59	1		*FRONT LOWER PANEL, CENTER (WCP)	Bent	1,118.40 F	*1,118.40 F
60	1		*FRONT BUMPER STEP PLATE, CENTER (WCP)	Cracked	561.60 F	*561.60 F
61	2		*FRONT BUMPER COVER, LH & RH (WCP)	Repair	4,478.88 F	*- F
62	1		*FRONT NUMBER PLATE HOLDER (WCP)	Missing	179.52 F	*179.52 F
63	2		*STEP COVER - UPPER, LH & RH (WCP)	Not Necessary	264.00 F	*- F
64	2		*FRONT WHEEL MUDGUARD SEAL (FRONT LONG), LH & RH (WCP)	Bent	365.00 F	*365.00 F
65	2		*REAR CABIN BRACKET - BOTTOM, LH & RH (WCP)	Bent	1,748.88 F	*1,748.88 F
66	1		*REAR CAB TILT LOCK, LH & RH (WCP)	O/S Bent / N/S Not Necessary	3,037.44 F	*1,518.72 F
67	2		*LOCK KEY, LH & RH (WCP)	Not Necessary	676.80 F	*- F
68	2		*REAR CABIN SPRING (SHOCK ABSORBER), LH & RH (WCP)	Bent	1,364.64 F	*1,364.64 F
69	1		*REAR CROSSLINK BRACKET, LH & RH (WCP)	O/S Bent / N/S Not Necessary	216.48 F	*108.24 F
70	1		*LINK, LH & RH (WCP)	O/S Bent / N/S Not Necessary	272.64 F	*136.32 F
71	1		*LINK WASHER, LH & RH (6PCS)(WCP)	O/S Necessary/N/S Not Necessary	99.36 F	*49.68 F
72	3		*SEALANT	Necessary	90.00 FS	*90.00 FS
73	1		*IU BRACKET STICKER	Necessary	5.00 FS	*5.00 FS
74	1		*FRONT NUMBER PLATE	Missing	30.00 FS	*30.00 FS
75	1		*RADIATOR COOLANT (25LIT)	Necessary	375.00 FS	*375.00 FS
76	1		*SUN VISOR, BOTTOM (WCP)	Deformed	540.15 F	*540.15 F
77	1		*RECIRCULATION SHIELD, FRONT UPPER PANEL (WCP)	Bent	143.91 F	*143.91 F
78	2		*CABIN LOCK BRACKET, LH & RH (WCP)	Bent	210.34 F	*210.34 F
79	1		*CONTACT HOUSING OUTER CASING (WCP)	Distorted	105.00 F	*105.00 F
80	2		*FRONT CABIN STOPPER (WCP)	Missing	36.00 F	*36.00 F
81	1		*CAB TILT STOP (WCP)	Bent	982.28 F	*982.28 F
82	1		*BLEED PIPE (WCP)	Cut	212.00 F	*212.00 F
83	1		*SET WATER HOSE ASSY (WCP)	Cut	225.00 F	*225.00 F
84	1		*WATER HOSE (WCP)	Cut	30.00 F	*30.00 F
85	2		*CHARGE AIR COOLER HOSE (WCP)	Distorted	270.00 F	*270.00 F
86	4		*HOSE CLAMP (WCP)	Bent	180.00 F	*180.00 F
87	2		*RADIATOR SIDE LINK, LH & RH (WCP)	Bent	476.32 F	*476.32 F
88	1		*RADIATOR SIDE BRACKET, RH (WCP)	Bent	53.30 F	*53.30 F
89	1		*RECIRCULATION SHIELD, RADIATOR (WCP)	Cracked	573.95 F	*573.95 F
90	1		*RADIATOR FAN COVER (WCP)	Cracked	708.24 F	*708.24 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
91	1		*FAN RING (WCP)	Distorted	929.37 F	*929.37 F
92	1		*FAN RING RUBBER (WCP)	Cut	360.62 F	*360.62 F
93	1		*SET FAN C/W FAN CLUTCH (WCP)	Cracked	1,660.00 F	*1,660.00 F
94	1		*FRONT LOWER PANEL, LH (WCP)	Bent	179.27 F	*179.27 F
95	1		*HEADLAMP PROTECTION MESH BRACKET (INNER), LH (WCP)	Bent	139.88 F	*139.88 F
96	1		*POWER STEERING SHAFT (WCP)	Bent	870.00 F	*870.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	78,191.63	61,092.23
+ Margin on L,N Items 10.00/10.00% (\$\$)	7,769.16	6,059.22
Total Parts (\$\$)	85,960.79	67,151.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISMANTLE AND REPLACE FRONT WINDSCREEN, INCLUDING APPLY SEALANT	New	350.00	300.00
2	TO DISMANTLE FRONT AND INTERIOR ATTACHED PARTS, SUCH AS INSTRUMENT PANELS, SEAT CUSHIONS, ALL PIPING / HOSES, WIRING HARNESS ETC. TO JACK, KNOCK AND STRAIGHTEN DASH PANEL & FLOOR PANEL. REMOVE AND REPLACE DAMAGED PARTS, REINSTALL NECESSARY PARTS. REALIGN FRONT CABIN ETC	New	4,200.00	2,800.00
3	REMOVE AND REPLACE CHARGE AIR COOLER & RADIATOR ETC	New	700.00	525.00
4	REMOVE AND REPLACE AIRCON CONDENSER, VACUUM AND REPLENISH AIRCON GAS	New	300.00	200.00
5	SPRAY PAINTING (INTERIOR & EXTERIOR)	New	1,000.00	800.00
6	TO REMOVE AND REPLACE WATER BLEED PIPE (ON TOP OF ENGINE), FAN RING & RUBBER, FAN ASSY	New	350.00	200.00
Gross Labour Cost (\$)			6,900.00	4,825.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >