

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS23000659/KNY3M4**Date:** 28/03/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SPCM1000000962
Claimant Vehicle No :	SMV5331S	Insured Vehicle No :	XB2282U
Date of Loss:	17/01/2023	Nature of Claim:	TP
		Claim No:	2023 32004691

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV5331S		
Make & Model:	MERCEDES-BENZ CLA180, 1.6 (R18 BI) (A)	Engine No:	27091030369366
Reg. Date:	06/05/2014 (Man. Year: 2014)	Chassis No:	WDD1173422N081122
Colour:	Metallic Black	Odometer:	148892 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,949.30	10,486.02	4,463.28	29.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,560.00	900.00	36.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,409.30	12,046.02	5,363.28	30.81
Approved Total (Overridden) (S\$)		9,000.00		
Nett Amount (S\$)	17,409.30	9,000.00	8,409.30	48.30
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	19/01/2023	
Date Inspected:	31/01/2023	Inspected At: LIAN HER MOTORS BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Mar 2023)
Parts:	143	MERCEDES-BENZ CLA180 1.6 (R18 BI) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV5331S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	2,030.00 FL	*2,030.00 FL
2	1		*FRONT BONNET LOCK	Repair	255.00 FL	*- FL
3	2		*FRONT HEADLAMP ASSY	Mtg Cracked	5,860.00 FL	*5,265.80 FL
4	1		*FRONT GRILLE	Cracked	805.00 FL	*805.00 FL
5	2		*FRONT GRILLE CHROME	Serviceable	570.00 FL	*- FL
6	1		*FRONT GRILLE EMBLEM	Necessary	85.00 FL	*85.00 FL
7	1		*FRONT BUMPER	Buckled/Mtg Distorted	1,581.00 FL	*1,377.00 FL
8	1		*FRONT BUMPER REINFORCEMENT	Cracked	850.00 FL	*850.00 FL
9	1		*FRONT BUMPER INNER LINING	Cracked	205.00 FL	*205.00 FL
10	1		*FRONT BUMPER SPONGE	Cracked	155.00 FL	*155.00 FL
11	1		*FRONT BUMPER LOWER GRILLE	Dented/Distorted	195.00 FL	*195.00 FL
12	1		*FRONT BUMPER LOWER LID	Serviceable	285.00 FL	*- FL
13	1		*FRONT BUMPER EMBLEM - LOGO	Necessary	65.00 FL	*65.00 FL
14	2		*FRONT BUMPER SENSOR	Serviceable	530.00 FL	*- FL
15	1		*FRONT SUPPORT PANEL	Serviceable	1,156.00 FL	*- FL
16	1		*AIR CLEANER AIR DUCT	Cracked	185.00 FL	*185.00 FL
17	1		*AIR CON CONDENSER	Serviceable	1,250.00 FL	*- FL
18	1		*FRONT NO PLATE HOLDER	Serviceable	115.00 FL	*- FL
19	2		*FRONT BUMPER SIDE PROTECTOR	Necessary	390.00 FS	*390.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,567.00	11,607.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,617.70	1,121.78
Total Parts (\$\$)	14,949.30	10,486.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING, WELDING AND CUTTING	New	1,000.00	650.00
2	TO PUTTY AND SPRAY PAINT	New	1,000.00	800.00
3	CHECK & RECONNECT WIRING	New	40.00	20.00
4	TO RESPRAY ANTI-RUST PROOFING TREATMENT	New	120.00	30.00
5	REMOVE/RENEW FRONT O/S BUMPER SENSOR AND TO RESET SAME	New	120.00	60.00
6	REMOVE/RENEW AIR CON CONDENSER AND TO TOP UP GAS	New	180.00	0.00
Gross Labour Cost (S\$)			2,460.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >