

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000660/UQP3Q2**Date:** 03/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00120492200
Claimant Vehicle No :	SLC4435U	Insured Vehicle No :	GBJ3777X
Date of Loss:	07/01/2023	Nature of Claim: TP	Claim No: SNM23D200272/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC4435U		
Make & Model:	SUBARU IMPREZA, 1.5 R AWD 4AT ABS AIRBAG (A)	Engine No:	EL15D675338
Reg. Date:	29/07/2010 (Man. Year: 2009)	Chassis No:	JF1GE3KS59G004562
Colour:	Red	Odometer:	175913 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,694.48	3,680.48	1,014.00	21.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	1,430.00	490.00	25.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,614.48	5,110.48	1,504.00	22.74
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	6,614.48	4,000.00	2,614.48	39.53
+ GST 8.00/8.00% (S\$)	529.16	320.00	209.16	39.53
Nett Amount (S\$)	7,143.64	4,320.00	2,823.64	39.53

INSPECTION

Date of Assignment: 19/01/2023

Date Inspected: 20/01/2023 Inspected At:

NO 1 KAKI BUKIT AVE 6

AUTOBAY #02-48

SINGAPORE 417883

Repairer: Focus Auto Pte Ltd (Kaki Bukit)

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Feb 2023)
Parts:	143	SUBARU IMPREZA 1.5 R AWD 4AT ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC4435U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Cracked	836.20 FL	*836.20 FL
2	1		*FRONT BONNET SEAL	Necessary	41.80 FL	*41.80 FL
3	2		*FRONT BONNET HINGE	Not Necessary	97.20 FL	*- FL
4	1		*FRONT FENDER -LH	Distorted	450.30 FL	*450.30 FL
5	1		*FRONT FENDER DUST COVER -LH	Torn	110.30 FL	*110.30 FL
6	6		*FRONT FENDER DUST COVER CLIP	Necessary	33.00 FL	*33.00 FL
7	1		*FRONT FENDER LAMP -LH	Not Necessary	45.20 FL	*- FL
8	1		*FRONT FENDER LOWER BRACKET -LH	Not Necessary	40.20 FL	*- FL
9	1		*FRONT SUPPORT PANEL	Repair	469.90 FL	*- FL
10	1		*FRONT HEADLAMP -LH	Broken	874.60 FL	*874.60 FL
11	1		*FRONT HEADLAMP LOWER BRACKET	Cracked	69.90 FL	*69.90 FL
12	1		*SET FRONT GRILLE /FRONT GRILLE MOULDING	Cracked	726.90 FL	*726.90 FL
13	5		*FRONT GRILLE CLIP	Necessary	5.50 FL	*5.50 FL
14	1		*FRONT BUMPER	Distorted	708.50 FL	*708.50 FL
15	1		*FRONT BUMPER SIDE RETAINER -LH	Cracked	15.80 FL	*15.80 FL
16	1		*FRONT BUMPER REINFORCEMENT	Repair	457.20 FL	*- FL
17	1		*FRONT BUMPER REINFORCEMENT COVER	Distorted	267.40 FL	*267.40 FL
18	1		*FRONT BUMPER FOG LAMP -LH	Cracked	352.20 FL	*352.20 FL
19	1		*FRONT BUMPER FOG LAMP SUPPORT-LH	Not Necessary	89.40 FL	*- FL
20	1		*FRONT LOWER PROTECTOR	Torn	108.20 FL	*108.20 FL
21	1		*FRONT BONNET LOCK	Not Necessary	68.40 FL	*- FL
Sub Total (S\$)						5,868.10 4,600.60
- List Item Discount on L Items 20.00/20.00% (S\$)						1,173.62 920.12
Total Parts (S\$)						4,694.48 3,680.48

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	950.00	550.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	60.00
4	SPRAY PAINTING	New	850.00	800.00
Gross Labour Cost (\$\$)			1,920.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >