

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23000662/KQP3Q2**Date:** 27/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00092402200		
<b>Claimant Vehicle No :</b>	SKH9196L	<b>Insured Vehicle No :</b>	GBK6894R		
Date of Loss:	18/01/2023	Nature of Claim:	TP	Claim No:	SNM23D200514/C02/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKH9196L</b>		Engine No:	1ZZ2514122
Make & Model:	TOYOTA WISH, 1.8 (A)		Chassis No:	ZNE100295688
Reg. Date:	22/07/2006 (Man. Year: 2006)		Odometer:	146800 km
Colour:	Metallic Grey			
Engine Capacity:	1794 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,521.95	6,394.48	9,127.47	58.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	1,970.00	3,710.00	65.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>21,201.95</b>	<b>8,364.48</b>	<b>12,837.47</b>	<b>60.55</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>6,600.00</b>		
<b>(\$\$)</b>	21,201.95	6,600.00	14,601.95	68.87
<b>+ GST 8.00/8.00% (\$\$)</b>	1,696.16	528.00	1,168.16	68.87
<b>Nett Amount (\$\$)</b>	<b>22,898.11</b>	<b>7,128.00</b>	<b>15,770.11</b>	<b>68.87</b>

**INSPECTION**

Date of Assignment:	25/01/2023	
Date Inspected:	19/01/2023	Inspected At: H C Auto Pte Ltd (HQ) 160 Sin Ming Drive, #05-09 Sin Ming Auto City Singapore 575722
Estimated Period of Repair:	5.0 days	

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Mar 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKH9196L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN GLASS	Shattered	1,359.80 FL	*980.00 FL
2	1		*REAR WINDSCREEN GLASS MOLDING	Necessary	298.35 FL	*116.00 FL
3	1		*TAIL GATE	Bent	1,243.10 FL	*1,243.10 FL
4	1		*TAIL GATE WEATHERSTRIP (50%)	Dented	238.50 FS	*159.00 FS
5	1		*TAIL GATE INNER LOCK	Dented	509.10 FL	*509.10 FL
6	1		*TAIL GATE INNER TRIM BOARD	Serviceable	428.22 FL	*- FL
7	1		*TAIL GATE TOYOTA LOGO	Necessary	71.60 FL	*71.60 FL
8	1		*TAIL GATE BOTTOM HOLDER	Serviceable	35.70 FL	*- FL
9	1		*TAIL GATE OUTER MOULDING (CHROME)	Mtg Cracked	227.57 FL	*227.57 FL
10	2		*TAIL GATE HINGE	Repair	116.60 FL	*- FL
11	2		*TAIL GATE DAMPER	Serviceable	471.00 FL	*- FL
12	2		*TAIL LAMP	Cracked	1,183.20 FL	*818.00 FL
13	2		*TAIL LAMP LOWER CLIP	Necessary	90.00 FL	*90.00 FL
14	1		*REAR BUMPER FASCIA	Buckled	1,377.10 FL	*590.00 FL
15	2		*REAR BUMPER SIDE RETAINER 1	Distorted	183.80 FL	*183.80 FL
16	2		*REAR BUMPER SIDE RETAINER 2	Distorted	87.00 FL	*87.00 FL
17	2		*REAR BUMPER STOPPER	Serviceable	93.10 FL	*- FL
18	2		*REAR BUMPER REFELCTOR	Serviceable	134.72 FL	*- FL
19	2		*REAR BUMPER BRACKET	Repair	96.88 FL	*- FL
20	2		*REAR BUMPER MUDFLAP	Serviceable	127.80 FL	*- FL
21	2		*REAR FENDER	Repair	1,822.80 FL	*- FL
22	2		*REAR FENDER INNER GARNISH	Mtg Cracked	1,418.60 FL	*1,418.60 FL
23	1		*REAR END PANEL	Bent	640.20 FL	*515.00 FL
24	1		*REAR END PANEL INNER GARNISH	Mtg Distorted	282.60 FL	*282.60 FL
25	1		*REAR FLOOR PANEL	Repair	696.42 FL	*- FL
26	1		*REAR SPARE TYRE CARRIER	Repair	312.40 FL	*- FL
27	1		*REAR SPARE TYRE BOARD (CENTRE)	Serviceable	587.80 FL	*- FL
28	2		*REAR SPARE TYRE BOARD (SIDE)	Serviceable	182.40 FL	*- FL
29	2		*REAR SPARE TYRE BOARD COVER (SIDE)	Serviceable	319.20 FL	*- FL
30	1		*REAR EXHAUST BOX	Repair	1,133.68 FL	*- FL
31	1		*REAR EXHAUST ALUMINIUM COVER	Serviceable	112.70 FL	*- FL
32	3		*REAR EXHAUST PIPE MOUNTING	Serviceable	80.60 FL	*- FL
33	1		*REAR LOCK SENSOR	Serviceable	595.69 FL	*- FL
34	1		*REAR WIPER MOTOR	Jammed	625.80 FL	*625.80 FL
35	1		*REAR WIPER ARM	Dented	155.80 FL	*155.80 FL
36	1		*REAR WIPER BLADE	Serviceable	36.60 FL	*- FL
37	1		*REAR END PANEL SEAL	Necessary	250.00 FS	*30.00 FS
38	1		*REAR REVERSE CAMERA	Serviceable	550.00 FS	*- FS
39	1		*IN CAR CAMERA	Serviceable	780.00 FS	*- FS
40	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
41	2		*REAR QUARTER GLASS INNER SEAL	Not Necessary	120.00 FS	*- FS
42	2		*REAR QUARTER GLASS INNER GUM	Not Necessary	120.00 FS	*- FS
43	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	60.00 FS	*30.00 FS
44	1		*REAR WINDSCREEN GLASS INNER GUM	Necessary	60.00 FS	*40.00 FS
45	1		*REAR NO PLATE	Serviceable	140.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (S\$)	19,806.43	8,372.97
					- List Item Discount on L Items 25.00/25.00% (S\$)	4,284.48	1,978.49
					Total Parts (S\$)	15,521.95	6,394.48

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES	New	2,200.00	800.00
2	TO PUTTY AND SPRAY PAINTING	New	1,800.00	800.00
3	TO CHECK REPAIR WIRING	New	100.00	20.00
4	TO TRANSFER TAIL GATE	New	120.00	60.00
5	RE-SEAL ANTI RUST	New	250.00	60.00
6	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	180.00	120.00
7	TO REMOVE AND REFIX O/S & N/S REAR QUARTER GLASS	New	240.00	0.00
8	REMOVE AND REFIX REVERSE SENSOR	New	100.00	50.00
9	TO REMOVE & REFIX FUEL PIPE	New	180.00	0.00
10	REMOVE AND REFIX EXHAUST PIPE	New	160.00	0.00
11	REMOVE AND REFIX CUSHION SEAT ,GARNISH ,CARPET ETC	New	350.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,680.00</b>	<b>1,970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >