

ASSESSMENT REPORT FOR VEHICLE NO. SFS 292 C

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	REAR BOOTLID	Repair	1,330.00	-
2	REAR TAILLAMP L/R	Reuse	1,154.20	-
1	REAR BUMPER	Cracked	1,670.99	1,670.99
1	REAR BUMPER REINFORCEMENT X ⁿⁿ	Bent	500.93	500.93 X
4	REAR BUMPER REVERSE SENSOR (1pc) @ 115	Cracked	1,057.20	1,057.20
4	REAR BUMPER REVERSE SENSOR 'O' RING @ 3.43	Cracked	74.00	74.00
4	REAR BUMPER REVERSE SENSOR HOLDER 1pc	Cracked	264.00	264.00
1	REAR BUMPER REVERSE SENSOR WIRE HARNESS X ⁿⁿ	Cut	173.00	173.00 X
2	REAR BUMPER SIDE RETAINER L/R X ⁿⁿ	Bent	151.50	151.50 X
2	REAR BUMPER SIDE BRACKET L/R X ⁿⁿ	Bent	96.00	96.00 X
1	REAR BUMPER INNER GARNISH X ⁿⁿ	Cracked	185.00	185.00 X
	REAR BUMPER NUMBER PLATE LAMP L/R X ⁿⁿ	Cracked	178.20	178.20 X
2	REAR BUMPER SIDE MOULDING L/R	Bent	210.00	210.00
1	REAR BUMPER CENTRE MOULDING	Cracked	300.99	300.99
1	REAR BUMPER REFLECTOR L/R RH (1pc)	Cracked	152.28	152.28
1	REAR BUMPER LOWER GARNISH	Cracked	135.00	135.00
1	REAR BUMPER LOWER SPOILER	Cracked	175.00	175.00
1	REAR BUMPER RH ALUMINIUM HEAT SHIELD X ⁿⁿ	Bent	193.00	193.00 X
1	REAR END PANEL ANTENNA SENSOR X ⁿⁿ	Faulty	189.00	189.00 X
1	REAR END PANEL	Repair	861.16	-
1	REAR EXHAUST SILENCER BOX	Repair	1,200.97	-
			10,252.42	5,706.09
Less 0% discount			-	-
Parts Total:			10,252.42	5,706.09

2388.61

102

2149.74

ASSESSMENT REPORT FOR VEHICLE NO. SFS 292 C

SPECIAL NETT ITEMS

1	REAR BUMPER ALUMINIUM HEAT SHIELD CLIPS - SET X11	Necessary	40.00	40.00 X
1	REAR BUMPER NUMBER PLATE	Cut	25.00	25.00
1	REAR BUMPER NUMBER PLATE HOLDER	Cut	50.00	50.00
1	REAR BUMPER ALUMINIUM HEAT SHIELD CLIPS - SET X11	Necessary	50.00	50.00 X
Special Nett Total :			165.00	165.00

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	120.00	100.00
2	To remove, reinstall top trim trim garnish, trim liner.	1140	100.00 nnX 80.00
3	To reset system after repair works.	250.00	100 200.00
4	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00	600 900.00
5	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,000.00	400 900.00
6	To apply anti-rust chemical on repaired and replaced panel.	80.00	X 60.00
Labour Total :		2,550.00	2,240.00
TOTAL (PARTS & LABOUR) \$		12,967.42	8,111.09

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

\$6,300.00

(SINGAPORE DOLLARS SIX THOUSAND THREE HUNDRED ONLY)



Amas Ong
Automobile Assessor

2149.74
 35.00
 1140.00
 3324.74
 202
 2659.79
 45-2,650 / 4 days