

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23000694/KQY3Q2**Date:** 21/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00084202201
<b>Claimant Vehicle No :</b>	SNC1585R	<b>Insured Vehicle No :</b>	SMK2665G
Date of Loss:	19/01/2023	Nature of Claim:	TP
		Claim No:	SNM23D200544/C02/CHNGPW

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SNC1585R</b>	Engine No:	1ZRY272301
Make & Model:	TOYOTA COROLLA, 1.6 (A)	Chassis No:	MR053REH104548369
Reg. Date:	15/09/2016 (Man. Year: 2016)	Odometer:	102677 km
Colour:	Metallic Pearl White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,485.00	547.50	937.50	63.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	950.00	1,100.00	53.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,535.00</b>	<b>1,497.50</b>	<b>2,037.50</b>	<b>57.64</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,200.00</b>		
<b>(S\$)</b>	3,535.00	1,200.00	2,335.00	66.05
<b>+ GST 8.00/8.00% (S\$)</b>	282.80	96.00	186.80	66.05
<b>Nett Amount (S\$)</b>	<b>3,817.80</b>	<b>1,296.00</b>	<b>2,521.80</b>	<b>66.05</b>

**INSPECTION**

Date of Assignment:	20/01/2023	
Date Inspected:	13/02/2023 Inspected At:	10 TUAS AVE 18 SINGAPORE 638894 Repairer:Goldbell Engineering Pte Ltd (Ang Mo Kio)
Estimated Period of Repair:	2.0 days	

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2023)
Parts:	143	TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC1585R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	730.00 F	*730.00 FL
2	1		*REAR BUMPER RETAINER LH	Serviceable	55.00 F	*- FL
3	1		*REAR BUMPER RETAINER RH	Serviceable	55.00 F	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Repair	250.00 F	*- FL
5	1		*REAR END PANEL TOP GARNISH	Serviceable	195.00 F	*- FL
6	1		*REVERSE SENSOR	Serviceable	200.00 FS	*- FS
					<b>Sub Total (S\$)</b>	<b>1,485.00 730.00</b>
					<b>- List Item Discount on L Items 0.00/25.00% (S\$)</b>	<b>0.00 182.50</b>
					<b>Total Parts (S\$)</b>	<b>1,485.00 547.50</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,REFIX & REPAIR AFFECTED DAMAGED PARTS .INCLUDING KNOCK OUT ,WELD AND STRAIGHTEN ON THE AFFECTED PARTS	New	1,200.00	600.00
2	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	150.00	0.00
3	TO PUTTY ,CLEAN ,SPRAY PAINT AND POLISH ETC	New	700.00	350.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,050.00</b>	<b>950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >