

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CT123000700/RQY3E2**Date:** 31/03/2023REFERENCEHandling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00099652200

**Claimant Vehicle  
No :** SKR805U**Insured Vehicle  
No :** YQ7556G

Date of Loss: 19/01/2023

Nature of Claim: TP

Claim  
No: SNM23D200545/C02/IRENEDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKR805U**

Make &amp; Model: TOYOTA WISH, 1.8 (A)

Engine No: 2ZR1493010

Reg. Date: 16/01/2015 (Man. Year: 2014)

Chassis No: JTDGG20W40J002063

Colour: Gold

Odometer: 105873 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,541.20	6,655.30	1,885.90	22.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,801.00	7,825.00	2,976.00	27.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>19,342.20</b>	<b>14,480.30</b>	<b>4,861.90</b>	<b>25.14</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>1,547.38</b>	<b>1,158.42</b>	<b>388.96</b>	<b>25.14</b>
<b>Nett Amount (S\$)</b>	<b>20,889.58</b>	<b>15,638.72</b>	<b>5,250.86</b>	<b>25.14</b>

INSPECTION

Date of Assignment: 20/01/2023

Date Inspected: 26/01/2023 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)  
2 Pandan Crescent  
Singapore 128462

Estimated Period of Repair: 9.0 days

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 31 Mar 2023)
<b>Parts:</b>	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKR805U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*SEALANT	Necessary	100.00 FS	*100.00 FS
3	1		*PLATE, RR BUMPER	Deformed	710.20 FS	*710.20 FS
4	1		*SUPPORT, RR BUMPER	Not Necessary	117.20 FS	*- FS
5	1		*SUPPORT, RR BUMPER	Not Necessary	117.20 FS	*- FS
6	1		*RETAINER, RR BUMPER	Not Necessary	55.30 FS	*- FS
7	1		*RETAINER, RR BUMPER	Not Necessary	55.30 FS	*- FS
8	4		*PIECE, RR BUMPER	Necessary	19.60 FS	*19.60 FS
9	1		*PANEL SUB-ASSY, BODY	Bent	644.90 FS	*644.90 FS
10	2		*ARM, RR BUMPER	Not Necessary	129.20 FS	*- FS
11	1		*PLATE, BACK DOOR	Not Necessary	358.30 FS	*- FS
12	1		*PANEL SUB-ASSY, BACK	Bent	1,775.90 FS	*1,775.90 FS
13	1		*GLASS SUB-ASSY, BACK	Broken	1,279.30 FS	*1,279.30 FS
14	2		*SIKA 182010 SIKA TACK GO! (BLA	Necessary	216.00 FS	*216.00 FS
15	1		*SIKA 207. G+P ADHESIVE PRIMER	Necessary	200.00 FS	*200.00 FS
16	1		*GARNISH, BACK DOOR	Cracked	348.60 FS	*348.60 FS
17	1		*LENS & BODY, RR	Cracked	353.40 FS	*353.40 FS
18	1		*LENS & BODY, RR	Cracked	353.40 FS	*353.40 FS
19	1		*LENS & BODY, RR	Not Necessary	425.90 FS	*- FS
20	1		*LENS & BODY, RR	Not Necessary	425.90 FS	*- FS
21	1		*EMBLEM, SYMBOL	Necessary	72.20 FS	*72.20 FS
22	1		*PLATE, LUGGAGE COMPT	Necessary	49.40 FS	*49.40 FS
23	1		*4T8 SENSOR	Not Necessary	151.60 FS	*- FS
24	1		*BACK SENSOR DARK SHERRY MM	Cracked	251.40 FS	*251.40 FS
25	1		*ANTENNA, ELECTRICAL	Cracked	231.00 FS	*231.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** **8,541.20** **6,655.30**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SUPPLY REGN PLATE (PO# )	New	80.00	0.00
2	RESET AND REPROGRAMME ECU	New	198.00	198.00
3	CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST	New	198.00	198.00
4	DRILL HOLE TO INSTALL REVERSE SENSOR	New	198.00	198.00
5	REMOVE TAIL-GATE COMPONENTS TO TRANSFER ONTO NEW DOOR	New	396.00	396.00
6	CLEAN UP BOOT INTERIOR BROKEN GLASSES	New	198.00	198.00
7	REPLACE REAR W/SCREEN GLASS	New	495.00	495.00
8	SUPPLY AND INSTALL REAR W/SCREEN SOLAR FILM	New	350.00	350.00
9	REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, TAIL-GATE, TAIL-LAMP PANEL AND AFFECTED PORTION OF CAR	New	4,752.00	3,168.00
10	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR	New	3,936.00	2,624.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,801.00</b>	<b>7,825.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >