

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23000701/APA3Q2
Date: 15/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210001827
Claimant Vehicle No :	SMJ23C	Insured Vehicle No :	SMX3390Z
Date of Loss:	02/01/2023	Nature of Claim:	TP
		Claim No:	6068104959SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ23C	Engine No:	B2941176N20B20B
Make & Model:	BMW 220i, 2.0 CONVERTIBLE HID NAV (A)	Chassis No:	WBA1L72050V491067
Reg. Date:	30/07/2015 (Man. Year: 2015)	Odometer:	51569 km
Colour:	Beige		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,908.16	307.35	2,600.81	89.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	480.00	800.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,188.16	787.35	3,400.81	81.20
+ GST 8.00/8.00% (S\$)	335.05	62.99	272.06	81.20
Nett Amount (S\$)	4,523.21	850.34	3,672.87	81.20
+ Loss of Use (3.0 x S\$90.00/day) (S\$)		270.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,122.34		

INSPECTION

Date of Assignment:	16/01/2023		
Date Inspected:	16/01/2023	Inspected At:	Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub Singapore 417921
Estimated Period of Repair:	2.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER ASSY	Repair	1,530.60 FL	*- FL
2	10		*FRT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
3	1		*FRT NO PLATE GARNISH BASE	Deformed	108.95 FL	*108.95 FL
4	2		*FRT PDC SENSOR	Not Necessary	796.70 FL	*- FL
5	1		*FRT BUMPER LOWER AIR GRILLE	Not Necessary	253.10 FL	*- FL
6	1		*FRT GRILLE ASSY RH	Damaged	152.55 FL	*152.55 FL
7	1		*AIRCON TEMPERATURE SENSOR	Not Necessary	121.95 FL	*- FL
8	1		*SET FRT NO.PLATE W/FRAME	Dented	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,058.85	336.50
- List Item Discount on L Items 5.00/10.00% (\$)	150.69	29.15
Total Parts (\$)	2,908.16	307.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	80.00	30.00
2	TO CHECK AIRCON SENSOR & TEMPERATURE SENSOR	New	250.00	0.00
3	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	500.00	200.00
4	TO PUTTY AND RESPRAY PAINTING ON FRT BUMPER	New	450.00	250.00
			Gross Labour Cost (\$\$)	480.00
			1,280.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >