

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23000708/APA3Q2**Date:** 18/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210013888
Claimant Vehicle No :	SKW2823C	Insured Vehicle No :	SMX9373J
Date of Loss:	06/01/2023	Nature of Claim:	TP
		Claim No:	6789491718SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW2823C	Engine No:	27492030407336
Make & Model:	MERCEDES-BENZ C200, 2.0 (A)	Chassis No:	WDD2050422R080182
Reg. Date:	23/10/2015 (Man. Year: 2015)	Odometer:	46470 km
Colour:	White		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,988.30	5,109.10	3,879.20	43.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	760.00	1,790.00	70.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,538.30	5,869.10	5,669.20	49.13
Approved Total (Overridden) (S\$)		4,700.00		
Nett Amount (S\$)	11,538.30	4,700.00	6,838.30	59.27
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		4,926.75		
Global Sum Settlement (S\$)		4,900.00		

INSPECTION

Date of Assignment:	10/01/2023	
Date Inspected:	10/01/2023	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	2.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,376.00 FL	*1,376.00 FL
2	1		*FRONT BUMPER LIP (BLACK)	Not Necessary	365.00 FL	*- FL
3	1		*FRONT BUMPER SIDE GRILLE RH	Cut	186.00 FL	*186.00 FL
4	2		*FRONT BUMPER SENSOR RH	Damaged	600.00 FL	*520.00 FL
5	6		*FRONT BUMPER SENSOR HOLDER	Necessary	384.00 FL	*150.00 FL
6	1		*FRONT BUMPER UPPER BEAM SIDE SUPPORT RH	Not Necessary	92.00 FL	*- FL
7	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	158.00 FL	*- FL
8	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	251.00 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	758.00 FL	*- FL
10	1		*FRONT BUMPER SPONGE	Cracked	217.00 FL	*217.00 FL
11	1		*FRONT BUMPER BOTTOM COVER GARNISH	Not Necessary	288.00 FL	*- FL
12	1		*FRONT HEADLAMP (LED) RH	Cracked	2,978.00 FL	*2,978.00 FL
13	1		*FRONT HEADLAMP LOWER BRACKET RH	Cracked	172.00 FL	*172.00 FL
14	1		*FRONT GRILLE WITH CHROME	Not Necessary	1,113.00 FL	*- FL
15	2		*FRONT GRILLE SIDE AIR GUARD	Not Necessary	156.00 FL	*- FL
16	1		*HORN	Not Necessary	195.00 FL	*- FL
17	1		*FRONT FENDER COWLING (FRONT) RH	Not Necessary	198.00 FL	*- FL
18	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
19	1		*SET FRONT BUMPER CLIP	Necessary	120.00 FS	*50.00 FS
20	1		*SET FRONT BUMPER SIDE GRILLE CLIP	Necessary	50.00 FS	*20.00 FS
21	1		*SET FRONT BUMPER BOTTOM COVER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
22	1		*SET FRONT NUMBER PLATE GARNISH CLIP	Not Necessary	50.00 FS	*- FS
23	1		*SET FRONT FENDER COWLING CLIPS	Not Necessary	80.00 FS	*- FS
24	1		*SET SUPPORT PANEL UNDER COVER GARNISH CLIP	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,937.00	5,669.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	948.70	559.90
Total Parts (\$\$)	8,988.30	5,109.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,200.00	300.00
2	SPRAY PAINTING TO AFFECTED AREA	New	800.00	400.00
3	REFOCUS HEADLAMP BEAM	New	80.00	0.00
4	REMOVE ADN REFIX SENSOR	New	120.00	60.00
5	TO CHECK DIAGNOSTICS OF VEHICLE MANEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	350.00	0.00
Gross Labour Cost (\$\$)			2,550.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >