

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG23000713/AYA3Q2**Date:** 19/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900120549
<b>Claimant Vehicle No :</b>	GBG6350P	<b>Insured Vehicle No :</b>	SMN1138C
Date of Loss:	28/12/2022	Nature of Claim:	TP
		Claim No:	8958074429SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBG6350P</b>	Engine No:	1KD2696670
Make & Model:	TOYOTA HIACE, 3.0 TURBO 4DR AT (A)	Chassis No:	JTFHT02P500219337
Reg. Date:	22/09/2017 (Man. Year: 2017)	Odometer:	168861 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,195.02	5,044.17	2,150.85	29.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	2,650.00	980.00	27.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,825.02</b>	<b>7,694.17</b>	<b>3,130.85</b>	<b>28.92</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,100.00</b>		
	<b>(S\$)</b>	10,825.02	6,100.00	4,725.02
<b>+ GST 8.00/8.00% (S\$)</b>	866.00	488.00	378.00	43.65
<b>Nett Amount (S\$)</b>	<b>11,691.02</b>	<b>6,588.00</b>	<b>5,103.02</b>	<b>43.65</b>
<b>+ Car Rental (10.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		1,070.00		
	<b>Nett Liability (S\$)</b>	<b>7,658.00</b>		

**INSPECTION**

Date of Assignment:	30/12/2022	Inspected At:	J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578 Singapore 539186
Date Inspected:	30/12/2022		
Estimated Period of Repair:	9.0 days		

**Adjuster:** ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,969.50 FL	*1,755.00 FL
2	1		*TOYOTA HIACE STICKER	Necessary	77.40 FL	*77.40 FL
3	1		*TAILGATE RUBBER	Not Necessary	395.00 FL	*- FL
4	1		*TAILGATE LOGO	Necessary	72.20 FL	*72.20 FL
5	1		*TAILGATE LOCK	Not Necessary	265.00 FL	*- FL
6	1		*REAR BUMPER	Distorted	595.00 FL	*595.00 FL
7	1		*REAR BUMPER RH RETAINER	Damaged	65.00 FL	*65.00 FL
8	6		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
9	1		*RH TAILLAMP	Cracked	300.80 FL	*300.80 FL
10	3		*RH TAILLAMP CLIPS	Necessary	15.00 FL	*15.00 FL
11	1		*RH TAILLAMP INNER PANEL	Dented	545.00 FL	*545.00 FL
12	1		*RH APRON PANEL	Damaged	100.00 FL	*100.00 FL
13	1		*RH APRON PANEL RETAINER	Damaged	35.00 FL	*35.00 FL
14	1		*REAR RH FENDER	Buckled	1,875.50 FL	*1,875.50 FL
15	1		*REAR RH AIR DUCT	Cracked	130.00 FL	*130.00 FL
16	1		*END PANEL INNER	Repair	890.00 FL	*- FL
17	1		*END PANEL OUTER	Dented	880.50 FL	*583.00 FL
18	1		*EXHAUST PIPE	Not Necessary	635.80 FL	*- FL
19	1		*RH HUP CAP	Cut	157.50 FS	*120.00 FS
20	1		*REAR W/SCREEN GUM	Necessary	50.00 FS	*30.00 FS
21	1		*REAR W/SCREEN SEAL	Necessary	30.00 FS	*30.00 FS
22	1		*6 PAX STICKER	Necessary	25.00 FS	*15.00 FS
23	1		*70KM/H STICKER	Necessary	25.00 FS	*15.00 FS
24	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,414.20</b>	<b>6,588.90</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	2,219.18	1,544.73
<b>Total Parts (\$\$)</b>	<b>7,195.02</b>	<b>5,044.17</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,600.00	1,200.00
2	SPRAY PAINTING	New	1,600.00	1,200.00
3	WIRING	New	30.00	30.00
4	REMOVE & REFIT REAR W/SCREEN	New	120.00	120.00
5	TRANSFER TAILGATE FITTING	New	80.00	60.00
6	REMOVE & REFIT EXHAUST PIPE	New	80.00	0.00
7	UPHOLSTERY	New	120.00	40.00
			<b>Gross Labour Cost (S\$)</b>	<b>2,650.00</b>
				<b>3,630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >