4/3/23, 9:12 AM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI23000714/RVY3Q2

03/04/2023 Date:

**REFERENCE** 

No:

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNA00223802206

Odometer:

**Claimant Vehicle** 

SDG19M

Insured Vehicle SJT6950U

Nature of Claim: TP

No:

Date of Loss: 17/01/2023

Claim No:

7250 km

SNM23D200496/C02/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SDG19M Reg No:

MERCEDES-BENZ E53, 3.0 4MATIC (A) 25693030488686 Make & Model: Engine No: Reg. Date: 29/06/2022 (Man. Year: 2022) Chassis No: W1K2130612B048480

Colour: Black

**Engine Capacity:** Market Value/New Car

2999 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 245/35Z R20 Rear Tyre Size: 245/35Z R20 Front Left Side: Rear Left Side: Yokohama 6 mm Yokohama 6 mm Front Right Side: Rear Right Side: Yokohama 6 mm Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,137.04	6,137.04	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	2,260.00	640.00	22.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,037.04	8,397.04	640.00	7.08
+ GST 8.00/8.00% (S\$)	722.96	671.76	51.20	7.08
Nett Amount (S\$)	9,760.00	9,068.80	691.20	7.08

**INSPECTION** 

Date Inspected:

Date of Assignment: 20/01/2023

> 188 PANDAN LOOP SINGAPORE 128378

10/02/2023 Inspected At:

Repairer: Cycle & Carriage Automotive Pte Ltd

(Pandan Gardens)

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/3/23, 9:12 AM Adjuster Report

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Mar 2023)

Parts: 143 MERCEDES-BENZ E53 3.0 4MATIC (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SDG19M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*LH/HEADLAMP UNIT	Cut	3,677.73 FS	*3,677.73 FS
2	1	*LH/FRONT BUMPER TRIM STRIP	Cracked	140.01 FS	*140.01 FS
3	12	*RIVET	Necessary	64.08 FS	*64.08 FS
4	1	*LH/SIDE FRONT BUMPER COVER	Scratched	139.86 FS	*139.86 FS
5	1	*FRONT AMG BUMPER	Scratched	2,091.76 FS	*2,091.76 FS
6	10	*BLACK BLIND RIVET	Necessary	23.60 FS	*23.60 FS
F=Fra	nchise part. S=SpcNe	ett.	_		
			Total Parts (S\$)	6,137.04	6,137.04

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	1,440.00	960.00
2	RESPRAY FRONT BUMPER	New	960.00	800.00
3	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	380.00
4	TO REMOVE,REPLACE HEADLAMP WITH FOCUS	New	120.00	120.00
	Gross Labou	r Cost (S\$)	2,900.00	2,260.00
	Report was unsubmitted during this	print-out		

< END OF ESTIMATES >