



ESTABLISHED 1984

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)

Ref: CS3/SPF23000716/Scy3m4

ACCIDENT CLAIMS SECTION (SPORE POLICE
FORCE) POLICE LOGISTICS BASE (PLB) 1
HEMMANT ROAD SINGAPORE 438675

Date: 24/07/2023

ATTN: HAFIZUL FARHAN

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

| | | | |
|---------------------|----------------------|-----------------------|------------|
| Insured Veh. | TP 416M | Veh. Inspected | SGP 2593A |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | ACS/105/009/2023/002 | Excess (\$) | 0.00 |
| Assign From | HAFIZUL FARHAN | Assign Date | 20/01/2023 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|-------------------|---------------------|--------------------|
| Make & Model | TOYOTA ALTIS | c.c | 1598 |
| Engine No. | HIDDEN | Year of Reg. | 2016 |
| Chassis No. | MR053REH104556251 | Colour | GREY |
| Odometer | 257350 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | FAIR | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|-----------------------|------------|--------|---------|
| R/H Front Tyre | 215/45 R17 | GOFORM | 5 mm |
| L/H Front Tyre | 215/45 R17 | GOFORM | 5 mm |
| R/H Rear Tyre | 215/45 R17 | GOFORM | 5 mm |
| L/H Rear Tyre | 215/45 R17 | GOFORM | 5 mm |

4. Description of DamagesTHE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S
BODY.

DAMAGES SEE DETAILS.

5. General Information

| | | | |
|-----------------------|---|----------------------------|-------------------------|
| Accident Date | 17/01/2023 | Inspect Date / Time | 26/01/2023 (12:00 PM) |
| Survey held at | APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800. | | |

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

| | |
|-------------------------------------|------------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 12 Working Days |
|-------------------------------------|------------------------|