

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23000717/AYA3Q2**Date:** 10/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700052615
Claimant Vehicle No :	SLL6663S	Insured Vehicle No :	SLS2322R
Date of Loss:	30/12/2022	Nature of Claim:	TP
		Claim No:	4204291679SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL6663S	Engine No:	27491031675735
Make & Model:	MERCEDES-BENZ C180, 1.6 (A)	Chassis No:	WDD2050402R479200
Reg. Date:	27/02/2019 (Man. Year: 2018)	Odometer:	52415 km
Colour:	Grey		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,330.14	5,900.52	12,429.62	67.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,960.00	2,180.00	2,780.00	56.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,290.14	8,080.52	15,209.62	65.30
Approved Total (Overridden) (S\$)		6,400.00		
Nett Amount (S\$)	23,290.14	6,400.00	16,890.14	72.52
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		6,846.75		

INSPECTION

Date of Assignment:	03/01/2023	HD Perfect Autowork Pte Ltd (HQ)
Date Inspected:	03/01/2023 Inspected At:	8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Estimated Period of Repair:	6.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	2,299.00 FL	*1,799.00 FL
2	1	*REAR BUMPER CENTRE FRAME	Not Necessary	232.00 FL	*- FL
3	1	*REAR BUMPER TOWING COVER	Not Necessary	88.00 FL	*- FL
4	1	*REAR BUMPER SIDE INNER GARNISH RH	Torn	532.00 FL	*138.00 FL
5	1	*REAR BUMPER REVERSE SENSOR (3 PCS)	Damaged (2 PCS ONLY)	795.00 FL	*530.00 FL
6	6	*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	402.00 FL	*120.00 FL
7	1	*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	798.00 FL	*- FL
8	2	*REAR BUMPER CENTER UPPER BRACKET	Not Necessary	156.00 FL	*- FL
9	1	*REAR BUMPER BOTTOM CENTER GARNISH	Not Necessary	185.00 FL	*- FL
10	1	*REAR BUMPER LOWER GARNISH	Cut	399.00 FL	*399.00 FL
11	1	*REAR BUMPER LOWER GARNISH CHROME	Cut	380.00 FL	*380.00 FL
12	2	*REAR BUMPER UPPER CORNER BRACKET	Not Necessary	358.00 FL	*- FL
13	1	*REAR BUMPER SIDE RETAINER	O/S Damaged	190.00 FL	*95.00 FL
14	1	*REAR BUMPER SMART SENSOR CONTROL UNIT	Not Necessary	374.00 FL	*- FL
15	1	*REAR BUMPER SMART SENSOR C/W BRACKET	Not Necessary	279.00 FL	*- FL
16	1	*REAR BUMPER REINFORCEMENT	Not Necessary	950.00 FL	*- FL
17	1	*REAR FENDER DRAIN GARNISH RH	Not Necessary	247.00 FL	*- FL
18	1	*REAR FENDER RH	Repair	2,640.00 FL	*- FL
19	1	*REAR WINDSCREEN GLASS C/W MOULDING RH	Not Necessary	1,980.00 FL	*- FL
20	1	*TAILLAMP	O/S Cracked	1,872.00 FL	*866.00 FL
21	1	*TAILLAMP PANEL RH	Dented	367.90 FL	*367.90 FL
22	1	*REAR AIR VENT RH	Not Necessary	95.80 FL	*- FL
23	1	*REAR AIR VENT PANEL RH	Dented	367.90 FL	*367.90 FL
24	1	*BOOTLID WEATHERSTRIP	Not Necessary	258.00 FL	*- FL
25	1	*REAR END PANEL	Dented	2,014.00 FL	*1,360.00 FL
26	1	*REAR END PANEL INNER GARNISH	Not Necessary	285.00 FL	*- FL
27	1	*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
28	1	*SET REAR BUMPER BOTTOM CENTER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
29	1	*SET REAR BUMPER LOWER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
30	1	*SET TAILLAMP CLIP	Necessary	50.00 FS	*10.00 FS
31	1	*REAR FENDER SEALANT RH	Not Necessary	80.00 FS	*- FS
32	1	*SET REAR FENDER DRAIN GARNISH CLIP	Not Necessary	80.00 FS	*- FS
33	1	*SET REAR FENDER COWLING CLIP	Not Necessary	50.00 FS	*- FS
34	1	*SET REAR FENDER INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
35	1	*REAR WINDSCREEN REPAIR KIT	Not Necessary	350.00 FS	*- FS
36	1	*REAR WINDSCREEN SOLAR FILM	Not Necessary	550.00 FS	*- FS
37	1	*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
38	1	*SET REAR END PANEL INNER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
39	1	*SET REAR FLOOR UNDER SIDE GARNISH CLIP RH	Necessary	80.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,184.60	6,542.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,854.46	642.28
Total Parts (\$\$)	18,330.14	5,900.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,500.00	900.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	900.00
3	TUFF COAT	New	350.00	60.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX SUNROK SENSOR	New	200.00	60.00
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	380.00	60.00
7	REMOVE & REFIX REAR WINDSCREEN	New	150.00	0.00
8	CONDUCT WATER SEEPAGE TEST	New	100.00	0.00
9	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	250.00	50.00
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	650.00	120.00
Gross Labour Cost (S\$)			4,960.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >