

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23000719/APA3Q2**Date:** 17/07/2023**REFERENCE**

| | | | |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 7220151881 |
| Claimant Vehicle No : | SKA3359K | Insured Vehicle No : | SMQ3636C |
| Date of Loss: | 03/01/2023 | Nature of Claim: | TP |
| | | Claim No: | 5789667976SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------------|-------------|-------------------|
| Reg No: | SKA3359K | Engine No: | CZCC13604 |
| Make & Model: | VOLKSWAGEN GOLF, 1.4 TSI CL RL (A) | Chassis No: | WVWZZZAUZLW134742 |
| Reg. Date: | 30/09/2020 (Man. Year: 2020) | Odometer: | 16249 km |
| Colour: | Black | | |
| Engine Capacity: | 1395 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 225/45 R17 | Rear Tyre Size: | 225/45 R17 |
| Front Left Side: | Pirelli 6 mm | Rear Left Side: | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 27,794.77 | 18,484.76 | 9,310.01 | 33.50 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 5,600.00 | 3,380.00 | 2,220.00 | 39.64 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 33,394.77 | 21,864.76 | 11,530.01 | 34.53 |
| Approved Total (Overridden) (S\$) | | 17,500.00 | | |
| Nett Amount (S\$) | 33,394.77 | 17,500.00 | 15,894.77 | 47.60 |
| + Loss of Use (11.0 x S\$50.00/day) (S\$) | | 550.00 | | |
| + Doc/Search Fee (S\$) | | 26.75 | | |
| Nett Liability (S\$) | | 18,076.75 | | |
| Global Sum Settlement (S\$) | | 18,050.00 | | |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 09/01/2023 | |
| Date Inspected: | 09/01/2023 Inspected At: | JL Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit Singapore 415875 |
| Estimated Period of Repair: | 10.0 days | |

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|-----------------------|-------------|--------------|
| 1 | 1 | | *TAILGATE | Distorted | 1,999.60 FL | *1,895.00 FL |
| 2 | 2 | | *TAILGATE DAMPER | Not Necessary | 377.92 FL | *- FL |
| 3 | 1 | | *TAILGATE EMBLEM GOLF | Necessary | 115.77 FL | *115.77 FL |
| 4 | 1 | | *TAILGATE WIPER MOTOR | Damaged | 525.30 FL | *525.30 FL |
| 5 | 1 | | *TAILGATE WIPER ARM | Cut | 198.88 FL | *198.88 FL |
| 6 | 1 | | *TAILGATE WIPER ARM BOLT COVER | Cut | 80.87 FL | *80.87 FL |
| 7 | 1 | | *TAILGATE INNER TRIM | Deformed | 438.96 FL | *438.96 FL |
| 8 | 2 | | *TAILGATE INNER SIDE TRIM | Cut | 391.06 FL | *391.06 FL |
| 9 | 1 | | *TAILGATE TOP LOCK | Damaged | 388.54 FL | *388.54 FL |
| 10 | 1 | | *TAILGATE TOP TRIM | Deformed | 256.35 FL | *256.35 FL |
| 11 | 1 | | *TAILGATE LOWER LOCK | Damaged | 568.75 FL | *568.75 FL |
| 12 | 1 | | *TAILGATE LOGO WITH HANDLE | Damaged | 996.55 FL | *335.00 FL |
| 13 | 1 | | *TAILGATE WINDSCREEN MOULDING C/W GLASS | Shattered | 1,511.60 FL | *1,511.60 FL |
| 14 | 1 | | *TAILGATE WEATHERSTRIP | Cut | 635.60 FL | *335.00 FL |
| 15 | 2 | | *TAILGATE LAMP | N/S Cracked / O/S Cut | 1,495.30 FL | *950.00 FL |
| 16 | 2 | | *TAIL LAMP | N/S Cracked / O/S Cut | 1,667.02 FL | *1,580.00 FL |
| 17 | 1 | | *TAIL LAMP PANEL LH | Dented | 482.70 FL | *482.70 FL |
| 18 | 1 | | *TAIL LAMP INNER PANEL LH | Dented | 446.50 FL | *446.50 FL |
| 19 | 1 | | *TAIL LAMP INNER WIPER PANEL LH | Repair | 388.96 FL | *- FL |
| 20 | 1 | | *REAR BUMPER | Deformed | 1,588.40 FL | *1,250.00 FL |
| 21 | 1 | | *REAR BUMPER DIFFUSER | Deformed | 498.50 FL | *498.50 FL |
| 22 | 1 | | *REAR BUMPER REFLECTOR LH | Not Necessary | 180.17 FL | *- FL |
| 23 | 2 | | *REAR BUMPER NUMBER PLATE LAMP | Not Necessary | 199.74 FL | *- FL |
| 24 | 1 | | *REAR BUMPER CENTER BEAM | Cracked | 41.60 FL | *41.60 FL |
| 25 | 2 | | *REAR BUMPER SIDE BRACKET | Damaged | 397.00 FL | *397.00 FL |
| 26 | 1 | | *REAR BUMPER REINFORCEMENT | Dented | 659.46 FL | *659.46 FL |
| 27 | 2 | | *REAR BUMPER REVERSE SENSOR | Damaged | 507.32 FL | *507.32 FL |
| 28 | 4 | | *REAR BUMPER REVERSE SENSOR HOLDER | Necessary | 363.88 FL | *363.88 FL |
| 29 | 1 | | *REAR FENDER LH | Buckled | 2,183.44 FL | *1,499.00 FL |
| 30 | 2 | | *REAR FENDER INNER TRIM | Deformed | 1,071.20 FL | *1,071.20 FL |
| 31 | 1 | | *REAR FENDER AIR VENT LH | Not Necessary | 102.71 FL | *- FL |
| 32 | 1 | | *REAR END PANEL | Dented | 1,599.60 FL | *1,037.00 FL |
| 33 | 1 | | *REAR END PANEL TOP GARNISH | Deformed | 346.87 FL | *346.87 FL |
| 34 | 1 | | *REAR FLOOR PANEL | Repair | 2,439.60 FL | *- FL |
| 35 | 1 | | *REAR FLOOR MAT | Not Necessary | 398.69 FL | *- FL |
| 36 | 1 | | *REAR FLOOR PANEL TOP BOARD | Deformed | 698.75 FL | *698.75 FL |
| 37 | 1 | | *REAR TOOLS SPONGE | Cracked | 189.98 FL | *189.98 FL |
| 38 | 1 | | *REAR SPARE TYRE BOLT | Not Necessary | 90.97 FL | *- FL |
| 39 | 1 | | *REAR EXHAUST PIPE | Not Necessary | 1,588.18 FL | *- FL |
| 40 | 2 | | *REAR EXHAUST MOUNTING | Not Necessary | 181.94 FL | *- FL |
| 41 | 1 | | *REAR EXHAUST INSULATOR | Not Necessary | 299.96 FL | *- FL |
| 42 | 1 | | *REAR NUMBER PLATE | Dented | 50.00 FS | *50.00 FS |
| 43 | 1 | | *SET REAR BUMPER CLIP | Necessary | 80.00 FS | *30.00 FS |
| 44 | 1 | | *REAR FENDER SEALANT | Necessary | 80.00 FS | *60.00 FS |
| 45 | 1 | | *SET REAR FENDER INNER TRIM CLIPS | Necessary | 80.00 FS | *30.00 FS |
| 46 | 1 | | *REAR FENDER COWLING CLIP | Not Necessary | 40.00 FS | *- FS |
| 47 | 1 | | *TAILGATE SEALANT | Not Necessary | 150.00 FS | *- FS |
| 48 | 1 | | *SET TAIL GATE INNER TRIM CLIP | Necessary | 80.00 FS | *30.00 FS |
| 49 | 1 | | *TAILGATE WINDSCREEN SEALANT | Necessary | 80.00 FS | *40.00 FS |
| 50 | 1 | | *TAILGATE WINDSCREEN INNER SEAL | Necessary | 60.00 FS | *30.00 FS |
| 51 | 1 | | *TAILGATE WINDSCREEN SOLAR FILM | Necessary | 150.00 FS | *150.00 FS |
| 52 | 1 | | *SET TAILLAMP CLIP | Necessary | 50.00 FS | *30.00 FS |
| 53 | 1 | | *SET REAR END PANEL TOP GARNISH CLIPS | Necessary | 30.00 FS | *20.00 FS |
| 54 | 1 | | *REAR END PANEL INSULATION SEAL | Necessary | 150.00 FS | *60.00 FS |
| 55 | 1 | | *REAR BRAKE DOWN SIGN BOARD | Deformed | 180.00 FS | *120.00 FS |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | |
|--|-----|----------|------------------------|-----------|--|------------------|------------------|
| 56 | 1 | | *VIDEO RECORDER | Missing | 800.00 FS | *680.00 FS | |
| F=Franchise part. S=SpcNett. L=ListItemDisc. | | | | | | | |
| | | | | | Sub Total (\$) | 30,654.19 | 20,390.84 |
| | | | | | - List Item Discount on L Items 10.00/10.00% (\$) | 2,859.42 | 1,906.08 |
| | | | | | Total Parts (\$) | 27,794.77 | 18,484.76 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|---------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO PANEL BEAT ,REMOVE AND REPLACE PARTS | New | 2,200.00 | 1,400.00 |
| 2 | TO SPRAY PAINT AFFECTED AREA | New | 1,600.00 | 1,200.00 |
| 3 | TUFF KOTE | New | 250.00 | 120.00 |
| 4 | WIRING AND BULB CHECK | New | 180.00 | 30.00 |
| 5 | REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR | New | 350.00 | 100.00 |
| 6 | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING | New | 80.00 | 50.00 |
| 7 | TRANFER TAILGATE MECHANISM | New | 80.00 | 80.00 |
| 8 | TO VACUUM GLASS FRAGMATS | New | 80.00 | 80.00 |
| 9 | REMOVE AND REFIX REAR EXHAUST PIPE | New | 180.00 | 0.00 |
| 10 | REMOVE AND REFIX TAILGATE WINDSCREEN | New | 120.00 | 120.00 |
| 11 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC | New | 380.00 | 150.00 |
| 12 | REPLACE REAR VIDEO RECORDER | New | 100.00 | 50.00 |
| | | | Gross Labour Cost (\$\$) | 3,380.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >