3/23/23, 11:32 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI23000729/SNCQ2

23/03/2023 Date:

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MN000206 **Claimant Vehicle**

SH7961M Insured Vehicle No: SLJ6299X No:

Date of Loss: 15/01/2023 Nature of Claim: ΤP Claim No: M2300365

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH7961M

HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) G4LEKU404268 Make & Model: Engine No: Reg. Date: 30/10/2019 (Man. Year: 2019) Chassis No: KMHC851CVLU188677

Colour: Odometer: 325772 km Blue

Engine Capacity: 1580 cc Market Value/New Car Price:

N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Good Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 195/65 R15 Rear Tyre Size: Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,119.76	1,225.60	2,894.16	70.25
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,550.00	1,330.00	220.00	14.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,680.76	2,566.60	3,114.16	54.82
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	5,680.76	2,050.00	3,630.76	63.91
+ GST 8.00/8.00% (S\$)	454.46	164.00	290.46	63.91
Nett Amount (S\$)	6,135.22	2,214.00	3,921.22	63.91

INSPECTION

Date of Assignment: 31/01/2023 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 17/01/2023 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqubal Manager: **HUEY YON**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Mar 2023)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH7961M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Cracked	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Cracked	451.25 FL	*451.25 FL
4	1		*REAR BUMPER LWR CTR MOULDING	Not Necessary	155.00 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Not Necessary	138.10 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Not Necessary	138.10 FL	*- FL
8	1		*BOOTLID	Repair	2,549.70 FL	*- FL
9	1		*EMBLEM HYBRID	Necessary	24.30 FL	*24.30 FL
10	1		*EMBLEM – IONIQ	Necessary	31.30 FL	*31.30 FL
11	1		*ANTENNA SMARTKEY	Not Necessary	40.50 FL	*- FL
12	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	*- FL
13	1		*REAR NUMBER PLATE WITH TRIM COVER	Cracked	55.00 F	*55.00 F
14	1		*BOOTLID COMFORT TEL NO STICKER	Necessary	40.00 F	*40.00 F
15	1		*BOOTLID COMFORT LOGO STICKER	Necessary	30.00 F	*30.00 F
16	1		*BOOTLID COMFORT APP STICKER	Necessary	30.00 F	*30.00 F
17	1		*REAR BUMPER REVERSE SENSOR	Scratched	180.00 F	*180.00 F
18	1		*RENEW ADVERTISEMENT STICKER	Necessary	100.00 F	*100.00 F
F=Fra	anchise	part. L=ListIt	emDisc.			
				Sub Total (S\$)	5,040.95	1,423.25
			- List Item Discount on L Items	20.00/20.00% (S\$)	921.19	197.65

Report was unsubmitted during this print-out.

Total Parts (S\$)

4,119.76

1,225.60

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Misc	cellan	neous Items			,
1	1	OD/TP Case (Insurer)		11.00	11.00
			Sub Total (S\$)	11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING	New	750.00	700.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	REMOVE/REFIX BOOTLID GLASS	New	120.00	80.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	50.00
		Gross Labour Cost (S\$)	1,550.00	1,330.00

Report was unsubmitted during this print-out. < END OF ESTIMATES >