6/28/23, 4:45 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. Our File No: CC3/AIG23000759/TVCM4

AIG Building, 78 Shenton Way, #09-16 Date: 28/06/2023 Singapore 079120

**REFERENCE** 

Insured/Claimant: BASMA HASSAN ASSAD Policy No: 1700085629

Date of Loss: 04/01/2023 Nature of Claim: OD Claim No: 8374529470SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SLU5639Y** 

Make & Model: AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A) DAX009672 Engine No:

Reg. Date: 06/12/2017 (Man. Year: 2017) Chassis No: WAUZZZFY0J2040581

Colour: Grey Odometer: 60234 km

1984 cc **Engine Capacity:** 

Market Value/New Car

S\$137,000.00 Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): Yes Footbrake (Serviceable): General Condition: Yes

Handbrake (Serviceable): Yes **Engine Modification:** Nο Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19 Front Left Side: Rear Left Side: Michelin 6 mm Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		18,156.00	3,366.40	14,789.60	81.46
Miscellaneous Items		0.00	0.00	0.00	
Labour		7,852.00	2,972.00	4,880.00	62.15
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	26,008.00	6,338.40	19,669.60	75.63
	+ GST 8.00/8.00% (S\$)	2,080.64	507.07	1,573.57	75.63
	Nett Amount (S\$)	28,088.64	6,845.47	21,243.17	75.63

**INSPECTION** 

Date of Assignment: 25/01/2023

281 ALEXANDRA ROAD SINGAPORE 159938 Date Inspected: 20/01/2023 Inspected At: REPAIRER: PREMIUM AUTOMOBILES PTE LTD

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER - LH	Cut	1,536.00 FS	*1,228.80 FS
2	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	133.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP - LH	Necessary	45.00 FS	*35.44 FS
4	1		*FRONT BUMPER GUIDE SECTION - LH	Cracked	46.00 FS	*36.32 FS
5	1		*FRONT FENDER - LH	Bent	1,607.00 FS	*1,285.60 FS
6	1		*FRONT FENDER BRACE - LH	Not Necessary	266.00 FS	*- FS
7	1		*FRONT FENDER BRACKET - LH	Not Necessary	21.00 FS	*- FS
8	1		*FRONT FENDER BRACKET CENTRE - LH	Not Necessary	21.00 FS	*- FS
9	1		*FRONT FENDER CLOSURE PANEL - LH	Cracked	37.00 FS	*29.20 FS
10	1		*FRONT FENDER CLOSURE PANEL COVER - LH	Cracked	47.00 FS	*37.44 FS
11	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	326.00 FS	*-FS
12	1		*FRONT WHEEL SPOILER - LH	Not Necessary	191.00 FS	*- FS
13	1		*FRONT WHEEL COVER - LH / RH (2PCS)	N/s Cut	1,504.00 FS	*601.20 FS
14	1		*INSCRIPTION S - LINE	Necessary	141.00 FS	*112.40 FS
15	1		*HEADLIGHT MOUNTING - LH	Not Necessary	140.00 FS	*- FS
16	1		*LED HEADLIGHT - LH	Not Necessary	9,226.00 FS	*- FS
17	1		*LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM	Not Necessary	162.00 FS	*- FS
18	1		*HOSE FOR HEADLIGHT WASHER SYSTEM	Not Necessary	150.00 FS	*- FS
19	1		*FRONT WHEEL RIM - LH	Not Necessary	2,153.00 FS	*- FS
20	1		*RUBBER VALVE	Not Necessary	4.00 FS	*- FS
21	1	part. S=Spc	*SUNDRIES	Not Necessary	400.00 FS	*-FS
Γ <b>−</b> ΓΙά	ancilise	ран. 3–3рс	NGU.	Total Parts (S\$)	18,156.00	3,366.40

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND BOTH WHEEL ARC TRIMS	New	4,100.00	1,300.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labour	Cost (S\$)	7,852.00	2,972.00
	Report was unsubmitted during this	orint-out.		

< END OF ESTIMATES >