

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CC3/AIG23000761/TVCM4**Date:** 06/07/2023**REFERENCE**

Insured/Claimant:	BASMA HASSAN ASSAD	Policy No:	1700085629
Date of Loss:	09/01/2023	Nature of Claim:	OD
		Claim No:	4536637534SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLU5639Y</b>		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX009672
Reg. Date:	06/12/2017 (Man. Year: 2017)	Chassis No:	WAUZZFY0J2040581
Colour:	Grey	Odometer:	60234 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$137,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	26,166.00	15,689.68	10,476.32	40.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,052.00	1,880.00	6,172.00	76.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>34,218.00</b>	<b>17,569.68</b>	<b>16,648.32</b>	<b>48.65</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>2,737.44</b>	<b>1,405.57</b>	<b>1,331.87</b>	<b>48.65</b>
<b>Nett Amount (S\$)</b>	<b>36,955.44</b>	<b>18,975.25</b>	<b>17,980.19</b>	<b>48.65</b>

**INSPECTION**

Date of Assignment:	25/01/2023	
Date Inspected:	20/01/2023	Inspected At: 281 ALEXANDRA ROAD SINGAPORE 159938 REPAIRER: PREMIUM AUTOMOBILES PTE LTD
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER - RH	Deformed	1,536.00 FS	*1,228.80 FS
2	1		*FRONT BUMPER CONNECTING PIECE - CENTER	Not Necessary	242.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP - RH	Not Necessary	45.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - RH	Cracked	133.00 FS	*106.40 FS
5	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	170.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Not Necessary	900.00 FS	*- FS
7	1		*FRONT BUMPER UNDERRUN BAR	Cut	614.00 FS	*491.20 FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Cracked	260.00 FS	*207.60 FS
9	1		*RADIATOR GRILLE	Cracked	4,155.00 FS	*3,324.00 FS
10	1		*INSCRIPTION QUATTRO	Necessary	118.00 FS	*94.00 FS
11	1		*RADIATOR GRILLE STRIKER PLATE	Cracked	288.00 FS	*230.40 FS
12	1		*FRONT AIR GUIDE GRILLE - RH	Cut	691.00 FS	*552.80 FS
13	1		*FRONT AIR GUIDE GRILLE END CAP - RH	Not Necessary	109.00 FS	*- FS
14	2		*LOCKING CLIP	Not Necessary	10.00 FS	*- FS
15	1		*FOAM FILLER PIECE	Cracked	210.00 FS	*168.00 FS
16	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	1,104.00 FS	*- FS
17	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	46.00 FS	*- FS
18	1		*FRONT BUMPER COVER	Cracked	152.00 FS	*121.60 FS
19	1		*STICKER CAUTION	Necessary	17.00 FS	*13.28 FS
20	1		*STICKER AIR CONDITIONER	Necessary	24.00 FS	*18.56 FS
21	2		*FRONT SENSOR - RH INNER / OUTER	Not Necessary	544.00 FS	*- FS
22	4		*SENSOR SEAL RING	Not Necessary	11.00 FS	*- FS
23	1		*HORN - RH	Not Necessary	220.00 FS	*- FS
24	1		*HEADLIGHT MOUNTING - RH	Cracked	140.00 FS	*111.60 FS
25	1		*LED HEADLIGHT - RH	Cut	9,226.00 FS	*7,380.80 FS
26	1		*LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM - RH	Not Necessary	162.00 FS	*- FS
27	1		*LED HEADLIGHT HOSE	Not Necessary	150.00 FS	*- FS
28	1		*FRONT BUMPER WIRING	Not Necessary	457.00 FS	*- FS
29	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	326.00 FS	*- FS
30	1		*FRONT WHEEL SPOILER - RH	Cracked	182.00 FS	*145.60 FS
31	2		*FRONT WHEEL COVER - LH / RH	Cracked	1,504.00 FS	*601.20 FS
32	1		*TEMP SENSOR BRACKET	Not Necessary	20.00 FS	*- FS
33	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	61.00 FS	*- FS
34	1		*RADIATOR AIR GUIDE - CENTER	Not Necessary	61.00 FS	*- FS
35	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	61.00 FS	*- FS
36	1		*RADIATOR AIR GUIDE - RH	Deformed	70.00 FS	*55.28 FS
37	1		*RADIATOR LOUVRE	Not Necessary	623.00 FS	*- FS
38	1		*FRONT NO. PLATE	Necessary	60.00 FS	*60.00 FS
39	1		*SUNDRIES	Necessary	500.00 FS	*7.36 FS
40	1		*CHARGE AIR COOLER (Supplementary)	Bent	964.00 FS	*771.20 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$)** **26,166.00** **15,689.68**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	400.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	0.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS	New	4,500.00	750.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	0.00
6	TO REMOVE AND RENEW CHARGE AIR COOLER (Supplementary)	New	480.00	480.00
7	TO REPAIR RHS FRONT FENDER (Supplementary)	New	800.00	250.00
<b>Gross Labour Cost (S\$)</b>			<b>8,052.00</b>	<b>1,880.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >