



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5507K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	GLASS.SIDE.4MM.GLAZING	CRACKED	436.00	436.00
1	VERTICAL WINDOW CAPPING	DISTORTED	276.00	276.00
1	GLASS.SIDE.4MM.GLAZING.O/N/S	CRACKED	250.00	250.00
10	SIKAFLEX 255 EXTRA BLACK (400 ML/SAU)	NECESSARY	120.42	120.42
1	SIKA PRIMER 206 G&P BLACK (250ML)	NECESSARY	40.00	40.00
1	POLYESTER PUTTY KANDE (2.5LT)	NECESSARY	17.50	17.50
			1,139.92	1,139.92
	<u>LABOUR</u>			
	SPRAY PAINT - GREEN;600ML;SG BUS		30.00	30.00
	TO REMOVE / REPLACE / REPAIR DAMAGE PARTS / ASSESSMENT BY WORKSHOP.		188.00	188.00
	TO REMOVE / REPLACE / REPAIR DAMAGE PARTS BY CONTRACTOR.		950.00	950.00
	TO REMOVE / REPLACE / REPAIR DAMAGE ADVERTISEMENT / GREEN LIVERY PANEL.		375.00	375.00
	DOWNTIME (DAYS).		1,263.93	-
	TOWING COST. (NPA)		-	-
			2,806.93	1,543.00
GRAND TOTAL			3,946.85	2,682.92
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				2,682.92

Report Ref No. CS/LPC23000766/Tqce2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.