

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000776/RCP3Q2**Date:** 18/07/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00102962202
Claimant Vehicle No :	SMC3614B	Insured Vehicle No :	YN8703H
Date of Loss:	20/01/2023	Nature of Claim:	TP
		Claim No:	SNM23D200549/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC3614B	Engine No:	LEB6553637
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GP71211220
Reg. Date:	29/06/2018 (Man. Year: 2018)	Odometer:	305321 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Windforce 6 mm	Rear Left Side:	Windforce 6 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,976.20	3,855.00	1,121.20	22.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,690.00	1,000.00	690.00	40.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,666.20	4,855.00	1,811.20	27.17
Approved Total (Overridden) (S\$)		3,900.00		
(S\$)	6,666.20	3,900.00	2,766.20	41.50
+ GST 8.00/8.00% (S\$)	533.30	312.00	221.30	41.50
Nett Amount (S\$)	7,199.50	4,212.00	2,987.50	41.50

INSPECTION

Date of Assignment:	25/01/2023	
Date Inspected:	26/01/2023	Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub Singapore 608581
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 17 Jul 2023)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC3614B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	1,194.00 FL	*1,194.00 FL
2	1		*BOOT LID LOCK	Not Necessary	158.00 FL	*- FL
3	2		*BOOT LID HINGES LH/RH	Not Necessary	100.00 FL	*- FL
4	1		*BOOTLID LAMP LH	Cracked	341.00 FL	*341.00 FL
5	1		*REAR WIPER SHORT ARM	Cracked	86.00 FL	*86.00 FL
6	1		*REAR WIPER MOTOR	Not Necessary	151.00 FL	*- FL
7	1		*BOOT LID CENTER CHROME	Cracked	384.00 FL	*384.00 FL
8	1		*BOOT LID LOGO BADGE	Necessary	25.00 FL	*25.00 FL
9	1		*BOOT LID EMBLEM SHUTTLE	Necessary	55.00 FL	*55.00 FL
10	1		*BOOT LID EMBLEM HYBRID	Necessary	71.00 FL	*71.00 FL
11	1		*BOOT LID INNER TRIM BOARD	Not Necessary	221.00 FL	*- FL
12	3		*REAR CAR PLATE CENTER LAMP	Not Necessary	147.00 FL	*- FL
13	1		*REAR WINDSCREEN MOULDING	Necessary	119.00 FL	*119.00 FL
14	1		*TAIL LAMP LH	Cracked	521.00 FL	*521.00 FL
15	1		*REAR BUMPER	Deformed	1,151.00 FL	*1,151.00 FL
16	1		*REAR BUMPER SIDE RETAINER LH /RH	N/S Necessary /O/S NotNecessay	56.00 FL	*28.00 FL
17	1		*END PANEL	Not Necessary	459.00 FL	*- FL
18	1		*REAR WINDSCREEN	Broken	500.00 FL	*500.00 FL
19	1		*REAR FLOOR BOARD (NPA)	Repair	0.00 FL	*- FL
20	1		*REAR BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
21	1		*WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
22	1		*REAR WINDSCREEN SOLAR FILM	Necessary	200.00 FS	*150.00 FS
23	1		*FRONT PRIVATE HIRER DECAL }	Necessary	50.00 FS	*40.00 FS
24	1		*REAR PRIVATE HIRER DECAL }	Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,124.00	4,750.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,147.80	895.00
Total Parts (\$\$)	4,976.20	3,855.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS, PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	New	800.00	400.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	600.00	400.00
3	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	30.00	30.00
4	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	60.00	40.00
5	TO REMOVE AND REPLACE REAR WINDSCREEN	New	100.00	100.00
6	TO CARRY OUT INTERIOR CLEANING ON THE SHATTERED REAR WINDSCREEN	New	100.00	30.00
			Gross Labour Cost (S\$)	1,690.00
				1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >