

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23000792/RVP3Q2  
**Date:** 16/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00183512204
<b>Claimant Vehicle No :</b>	SKZ3318Y	<b>Insured Vehicle No :</b>	SJJ2573D
Date of Loss:	25/01/2023	Nature of Claim: TP	Claim No: SNM23D200598/C02/TOHHS

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKZ3318Y</b>		
Make & Model:	MERCEDES-BENZ B200, 1.6 STYLE (R16 LED) (A)	Engine No:	27091030851555
Reg. Date:	25/01/2016 (Man. Year: 2015)	Chassis No:	WDD2462422J377342
Colour:	Grey	Odometer:	141916 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,761.07	8,512.17	2,248.90	20.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,840.00	12,840.00	4,000.00	23.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>27,601.07</b>	<b>21,352.17</b>	<b>6,248.90</b>	<b>22.64</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>2,208.09</b>	<b>1,708.17</b>	<b>499.92</b>	<b>22.64</b>
<b>Nett Amount (S\$)</b>	<b>29,809.16</b>	<b>23,060.34</b>	<b>6,748.82</b>	<b>22.64</b>

**INSPECTION**

Date of Assignment:	01/02/2023	
Date Inspected:	10/02/2023 Inspected At:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378
Estimated Period of Repair:	13.0 days	

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 16 May 2023)
<b>Parts:</b> 144	MERCEDES-BENZ B200 1.6 STYLE (R16 LED) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKZ3318Y)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHF DOOR	Repair	1,872.27 FS	*- FS
2	1		*RIGHT REAR DOOR	Buckled	2,085.70 FS	*2,085.70 FS
3	1		*ABSORBING -RHR DOOR	Necessary	74.42 FS	*74.42 FS
4	1		*RHR DOOR WEATHERSTRIP	Necessary	317.72 FS	*317.72 FS
5	9		*BLIND RIVET WITH PAN HEAD	Necessary	24.30 FS	*24.30 FS
6	1		*RH/R DOOR WINDOW RUN	Not Necessary	137.50 FS	*- FS
7	1		*REAR BUMPER	Cut	1,607.14 FS	*1,607.14 FS
8	1		*RHS RUNNING BOARD	Cut	394.69 FS	*394.69 FS
9	1		*REAR RIGHT FENDER	Buckled	2,839.83 FS	*2,839.83 FS
10	1		*RH/ REAR FENDER AIR FLAP	Not Necessary	81.43 FS	*- FS
11	1		*RHR FENDER LINEAR	Not Necessary	157.70 FS	*- FS
12	1		*RH/R FENDER 3/4 GLASS	Necessary	239.65 FS	*239.65 FS
13	1		*MOUNTING CLIP	Necessary	11.94 FS	*11.94 FS
14	2		*MOUNTING CLIP	Necessary	11.24 FS	*11.24 FS
15	8		*RIVET	Necessary	48.72 FS	*48.72 FS
16	5		*RIVET	Necessary	15.10 FS	*15.10 FS
17	1		*CLIP	Necessary	5.03 FS	*5.03 FS
18	1		*TWO-COMPONENT ADHESIVE	Necessary	118.43 FS	*118.43 FS
19	1		*SEAM SEAL	Necessary	116.42 FS	*116.42 FS
20	1		*RHR DISK WHEEL	Scratched	601.84 FS	*601.84 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>10,761.07</b>	<b>8,512.17</b>
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	380.00
2	REMOVE & TRANSFER DOOR MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR	New	400.00	400.00
3	REMOVE CARRIAGE ASSY FROM FRAME ,IMPACT ,REPLACE AND ASSEMBLY WHEEL BASE & ADJUST TO VEHICLE	New	1,920.00	960.00
4	TO INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT	New	540.00	540.00
5	REMOVE & INSTALL INTERIOR SEATS ,CARPET ,GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR	New	2,880.00	1,920.00
6	TRANSFER RIM AND BALANCING TYRE	New	60.00	60.00
7	PANEL BEAT TO REPAIR AFFECTED AREAS,REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	5,760.00	5,280.00
8	RESPRAY ON RHF DR ,RHR DR ,RHR FENDER ,REAR BUMPER ,RIGHT RUNNING BOARD AND ACCIDENT AFFECTED AREA	New	4,800.00	3,200.00
9	SUPPLY & INSTALL HUPER OPTIK WINDOW FILM	New	100.00	100.00
			<b>Gross Labour Cost (S\$)</b>	<b>16,840.00</b>
				<b>12,840.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >